



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V

Enclosure 4

1450 MARIA LANE, SUITE 210  
WALNUT CREEK, CALIFORNIA 94596

October 27, 1982

Docket No. 50-397

Washington Public Power Supply System  
P. O. Box 968  
Richland, Washington 99352

Attention: Dr. R. G. Matlock  
Program Director

Gentlemen:

Subject: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE (SALP)

The NRC Region V SALP Review Board met on September 20, 1982, and evaluated the performance of the licensed activities at the Washington Nuclear Project No. 2. The draft report of our assessment is enclosed.

Several functional areas were considered areas of weakness requiring additional NRC and Washington Public Power Supply System attention, particularly with regard to increasing management involvement and control of the identified activities, as discussed in Section IV of the enclosed report.

We will meet with you on November 3, 1982, to discuss our assessment, your plans to improve performance, and any comments you may have regarding our report.

Please inform us in writing within twenty days from the date of this meeting of those actions that you have taken or will take to improve performance in the above areas of weakness. Additionally, you may also include any comments you may have regarding the SALP report.

Following our meeting and receipt of your response, the enclosed report, your response, and a summary of our findings and planned actions will be placed in the NRC Public Document Room.

Your cooperation is appreciated.

Sincerely,

D. M. Sternberg  
SALP Board Chairman and Chief,  
Reactor Projects Branch No. 1

Enclosure:  
As stated

cc w/enclosure:  
R. B. Glasscock, WPPSS  
C. S. Carlisle, WPPSS

8212170103 821210  
PDR ADDCK 05000397  
Q PDR

