

SAFEGUARDS INFORMATION

October 12, 2017

Mr. Bryan Hanson, Senior Vice President and
Chief Nuclear Officer
Exelon Generation Company, LLC
(CNO) Exelon Nuclear
4300 Winfield Road
Warrenville, Illinois 60555

SUBJECT: CLINTON POWER STATION, UNIT 1- NRC SECURITY INSPECTION REPORT
05000461/2017201

Dear Mr. Hanson:

On September 5, 2017, the U.S. Nuclear Regulatory Commission (NRC) completed a security inspection at your Clinton Power Station, Unit 1. The NRC inspectors discussed results of this inspection with Mr. Ted Stoner, Site Vice President, and other members of your staff. The results of this inspection are documented in the enclosed inspection report.

The NRC inspectors documented one finding of very low security significance (Green) in this report. This finding involved a violation of NRC requirements. The NRC is treating this violation as a non-cited violation (NCV) consistent with Section 2.3.2.a of the Enforcement Policy.

If you contest this violation or the significance of this NCV, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington DC 20555-0001; with copies to the Regional Administrator, Region III; the Director, Office of Nuclear Security and Incident Response; the Director, Office of Enforcement; and the NRC resident inspector at the Clinton Power Station, Unit 1.

If you disagree with a cross-cutting aspect assignment or a finding not associated with a regulatory requirement in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your disagreement, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC 20555-0001; with copies to the Regional Administrator, Region III; the Director, Office of Nuclear Security, and Incident Response; and the NRC resident inspector at the Clinton Power Station, Unit 1.

<p>The enclosure transmitted herewith contains Safeguards Information. When separated from the enclosure, this transmittal document is decontrolled.</p>
--

SAFEGUARDS INFORMATION

~~SAFEGUARDS INFORMATION~~

B. Hanson

2

One cross-cutting aspect was assigned to a finding in the area of Human Performance, within the area of Work Management. Specifically, because the licensee failed to implement a process controlling and executing work activities such that nuclear safety is the overriding priority (H.5).

This letter will be available for public inspection and copying at <http://www.nrc.gov/reading-rm/adams.html> and at the NRC Public Document Room in accordance with Title 10 of *the Code of Federal Regulations* (10 CFR) 2.390, "Public Inspections, Exemptions, Request for Withholding."

The enclosed report contains Safeguards Information (SGI) as defined by 10 CFR 73.21, "Protection of Safeguards Information: Performance Requirements," and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material in the enclosed report will not be made publicly available. If you choose to provide a response that contains SGI, please provide the level of protection described in 10 CFR 73.21. Otherwise, if you choose to provide a response that contains Security-Related Information, please mark your entire response "Security-Related Information - Withhold from Public Disclosure Under 10 CFR 2.390" in accordance with 10 CFR 2.390(d)(1) and follow the instructions for withholding in 10 CFR 2.390(b)(1). In accordance with 10 CFR 2.390(b)(1)(ii), the NRC is waiving the affidavit requirements for your response.

Sincerely,

/RA D. Johnson for/

Robert C. Johnson, Chief
Security Performance Evaluation Branch
Division of Security Operations
Office of Nuclear Security and Incident Response

Docket No. 50-461
License No. NPF-62

Nonpublic Enclosure:
Inspection Report 05000461/2017201 w/Attachments: Supplemental Information

cc w/ Enclosure: A. Siegmund, Clinton Power Station

~~SAFEGUARDS INFORMATION~~

SAFEGUARDS INFORMATION

B. Hanson

3

SUBJECT: CLINTON POWER STATION, UNIT 1 - NRC SECURITY INSPECTION
REPORT 05000461/2017201

DATE: OCTOBER 12, 2017

DISTRIBUTION W/O ENCL:

D. McIntyre, OPA-HQ
V. Mitlyng, PA-RIII
P. Chandrathil, PA-III
A. Barker, RSLO-RIII
H. Logaras, RSLO-RIII
N. Simonian, NSIR

DISTRIBUTION W/ENCL:

R. McKinley, RI
B. Desai, RII
K. Riemer, RIII
J. Groom, RIV

ADAMS ACCESSION NUMBER: ML17278A501

17278A501 Entire Report: <input type="checkbox"/> SUNSI Review Complete By:		<input type="checkbox"/> Non-Sensitive <input checked="" type="checkbox"/> Sensitive		<input type="checkbox"/> Publicly Available <input checked="" type="checkbox"/> Non-Publicly Available	
Cover Letter Only: <input type="checkbox"/> SUNSI Review Complete By:		<input checked="" type="checkbox"/> Non-Sensitive <input type="checkbox"/> Sensitive		<input checked="" type="checkbox"/> Publicly Available <input type="checkbox"/> Non-Publicly Available	
OFFICE	NSIR/DSO	NSIR/DSO	NSIR/DSO/	RIII	NSIR/DSO/SPEB
NAME	C. Roundtree	J. Clark	E. Byre	K. Riemer	C. Johnson
SIGNATURE				Via email	DJohnson for
DATE	5/10/17	10/10/17	10/9/17	10/12/17	1/12/17

OFFICIAL RECORD COPY**SAFEGUARDS INFORMATION**