

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8603040384 DOC. DATE: 86/02/27 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME : AUTHOR AFFILIATION
 SORENSEN, G. C. Washington Public Power Supply System
 RECIP. NAME RECIPIENT AFFILIATION
 ADENSAM, E. G. BWR Project Directorate 3

SUBJECT: Advises that rept detailing cause, length & date for each ECCS sys outage, required by NUREG-0737, Item II. k. 3. 17, will no longer be submitted, per 860219 telcon. App B to FSAR will be revised accordingly.

DISTRIBUTION CODE: A046D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: TMI Action Plan Rgmt NUREG-0737 & NUREG-0660

NOTES:

| | RECIPIENT | | COPIES | | | RECIPIENT | | COPIES | |
|-----------|-----------------|-----------|--------|------|--------------------|-----------|-----------|--------|------|
| | ID | CODE/NAME | LTTR | ENCL | | ID | CODE/NAME | LTTR | ENCL |
| | BWR | ADTS | 1 | 1 | BWR | PD3 PD 01 | 5 | 5 | |
| | BWR | EB | 1 | 1 | BWR | EICSB | 1 | 1 | |
| | BWR | FOB | 1 | 1 | BRADFUTE, J | | 1 | 1 | |
| | BWR | PSB | 1 | 1 | BWR | RSB | 1 | 1 | |
| INTERNAL: | ACRS | 34 | 10 | 10 | ADM/LFMB | | 1 | 0 | |
| | ELD/HDS2 | | 1 | 0 | IE/DEPER DIR 33 | | 1 | 1 | |
| | IE/DEPER/EPB | | 3 | 3 | NRR BWR ADTS | | 1 | 1 | |
| | NRR PAULSON, W. | | 1 | 1 | NRR PWR-A ADTS | | 1 | 1 | |
| | NRR PWR-B ADTS | | 1 | 1 | NRR/DHFT | | 1 | 1 | |
| | NRR/ORAS 18 | | 3 | 3 | <u>REG FILE</u> 04 | | 1 | 1 | |
| | RGN5 | | 1 | 1 | | | | | |
| EXTERNAL: | 24X | | 1 | 1 | LPDR 03 | | 1 | 1 | |
| | NRC PDR 02 | | 1 | 1 | NSIC 05 | | 1 | 1 | |

TOTAL NUMBER OF COPIES REQUIRED: LTTR 42 ENCL 40

1
THE UNIVERSITY OF CHICAGO
DEPARTMENT OF CHEMISTRY
57 SOUTH EAST ASIAN AVENUE
CHICAGO, ILLINOIS 60607
TEL: 773-936-3700
FAX: 773-936-3701
WWW: WWW.CHEM.UCHICAGO.EDU

| NAME | ADDRESS | CITY | STATE | ZIP |
|---------------------|------------------|-----------|-------|-------|
| ALAN B. BROWN | 1000 N. MICHIGAN | ANN ARBOR | MI | 48106 |
| JOHN D. HARRIS | 215 N. STATE | CHICAGO | IL | 60601 |
| ROBERT L. MASON | 1200 N. LAUREL | CHICAGO | IL | 60610 |
| WILLIAM E. SMITH | 500 N. LAUREL | CHICAGO | IL | 60610 |
| DAVID A. TAYLOR | 1500 N. LAUREL | CHICAGO | IL | 60610 |
| CHARLES F. WALKER | 200 N. LAUREL | CHICAGO | IL | 60610 |
| STEPHEN G. YOUNG | 300 N. LAUREL | CHICAGO | IL | 60610 |
| THOMAS H. ZIMMERMAN | 400 N. LAUREL | CHICAGO | IL | 60610 |

H

Washington Public Power Supply System

3000 George Washington Way P.O. Box 968 Richland, Washington 99352-0968 (509)372-5000

February 27, 1986
G02-86-180

8603040384 860227
PDR ADDOCK 05000397
P PDR

Docket No. 50-397

Director of Nuclear Reactor Regulation
Attn: E. G. Adensam, Project Director
BWR Project Directorate No. 3
Division of BWR Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Ms. Adensam:

Subject: NUCLEAR PLANT NO. 2
EMERGENCY CORE COOLING SYSTEM OUTAGE REPORTING

Reference: NUREG-0737, "Clarification of TMI Action Plan
Requirements", November 1980

Item II.K.3.17 of the referenced NUREG requires that a report be submitted detailing cause, length, and date for each emergency core cooling (ECC) system outage. The purpose of this report was to provide the staff with a quantification of historical unreliability due to test and maintenance outages. In a phone conversation on February 19, 1986, Mr. J. O. Bradfute of your staff advised the Supply System that the NRC Staff no longer requires this information. Accordingly, the Supply System will no longer be providing the subject report. Appendix B of the WNP-2 FSAR (WNP-2 Response to Regulatory Issues Resulting From TMI-2) will be revised accordingly in the next annual update.

Should you have any questions please contact Mr. P. L. Powell, Manager, WNP-2 Licensing.

Very truly yours,



G. C. Sorensen, Manager
Regulatory Programs

PLP/tmh

cc: JO Bradfute - NRC
JB Martin - NRC RV
E Revell - BPA
NS Reynolds - BLCP&R
NRC Site Inspector

A046
1/0



7