U. S. NUCLEAR REGULATORY COMMISSION

REGION V

Report No.	50-397/86-33	
Docket No.	50-397	
Licensee:	Washington Public Power Supply System P. O. Box 968 Richland, WA 99352	
Facility Name:	Washington Nuclear Project No. 2 WNP-2)	
Inspection at:	WNP-2 Site near Richland, Washington	
Inspection Conducted: October 14-17, 1986		
Inspectors:	C. Caldwell, Reactor Inspector Date Sa	7 /86 gned
	P. Qualls, Reactor Inspector Date Si	<i>ISG</i> gned
Approved by:	P. H. Johnson, Chief Reactor Projects Section 3	gned

Summary:

Inspection on October 14-17, 1986 (50-397/86-32)

<u>Areas Inspected</u>: Routine inspection by region based inspectors of the calibration program, licensee event reports and licensee action on previous inspection findings. During this inspection, Inspection Procedures 30703, 81707, 56700, 92712, 92700 and 92701 were utilized.

<u>Results</u>: No violations or deviations were identified.

> > ι


bcc w/enclosure: RSB/Document Control Desk (RIDS) Project Inspector Resident Inspector G. Cook B. Faulkenberry J. Martin

OCT 29 1986

1× 1)

, i

bcc w/o enclosure: LFMB



 $\left(\right)$

ł Ļ 5 A 30 ē, · ⊢∦.[₩]κ¹≱€ι

11

1

ե

\$ 10 ь ⁵

Å.,

dù31+

4

1.1

2.2484

