ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATOR INFORMATION DISTRIBUTION VSTEM (RIDS)

F

I

Ι

S

Å

Ľ

I

S

R

I

D

S

D

D

S

ACCESSION NBR:8811160374 DOC.DATE: 88/10/28 NOTARIZED: NO DOCKET # FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397 AUTH.NAME AUTHOR AFFILIATION ZIMMERMAN,R.P. Region 5, Ofc of the Director RECIP.NAME RECIPIENT AFFILIATION SORENSEN,G.C. Washington Public Power Supply System

SUBJECT: Forwards Insp Rept 50-397/88-30 on 880820-0930.No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR $\frac{1}{1}$ ENCL $\frac{1}{1}$ SIZE: $\frac{2+15}{1}$ TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24





a

t

ł

٠,

•

,

•

¢

OCT 2 3 1988

Docket No. 50-397

Washington Public Power Supply System P. O. Box 968 Richland, Washington 99352

Attention: Mr. G. C. Sorensen Manager of Regulatory Programs

Gentlemen:

Subject: NRC Inspection

This refers to the inspection conducted by Messrs. C. J. Bosted and R. C. Sorensen of this office on August 20 - September 30, 1988 of activities authorized by NRC Operating License No. NPF-21, and to the discussions of findings held by the inspectors with Mr. C. Powers and other members of the Supply System's staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel and observations by the inspectors.

No violations of NRC requirements were identified within the scope of this inspection.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely, DP/SAM SIGNE R. P. Zimmerman, Chief Reactor Projects Branch

Enclosure: Inspection Report No. 50-397/88-30

cc w/enclosure:

- A. L. Oxsen, WPPSS Director, Operations
- G. D. Bouchey, WPPSS Director, Licensing & Assurance
- C. M. Powers, WNP-2 Plant Manager
- A. G. Hosler, WNP-2 Licensing Manager
- G. E. Doupe, Esq.
- N. S. Reynolds, Debevois, Cook, Purcell & Reynolds


State of Washington

8811160374 881028 PDR ADOCK 05000397 Q PNU



OCT_2'3 1988

-2-



, ۰...

`

.

.

• ; ,

.