R

S

R

D

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ESSION NBR:8904040165 DOC.DATE: 89/03/16 NOTARIZED: NO DOCKET #
FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
AUTH.NAME AUTHOR AFFILIATION
YUHAS,G.P. Region 5, Ofc of the Director

RECIP.NAME RECIPIENT AFFILIATION
SORENSEN,G.C. Washington Public Power Supply System

SUBJECT: Forwards Insp Rept 50-397/89-09 on 890221-24 & notice of

violation.


DISTRIBUTION CODE: IE35D COPIES RECEIVED: LTR LENCL SIZE: 4+100 TITLE: Emergency Preparedness-Appraisal/Confirmatory Action Ltr/Exercise Rep

NOTES:

	RECIPIENT ID CODE/NAME PD5 PD	COPIE LTTR 1		RECIPIENT ID CODE/NAME SAMWORTH,R	COPI LTTR 1		/ A
	ARM/DAF/LFMB NRR/PMAS/ILRB12 REG_FILE 02 RGN2/DRSS/EPRPB	1 1 1	0 1 1	NRR/DREP/EPB 10 NUDOCS-ABSTRACT RGN5 FILE 01	1 1 1	1 1 1	D D
EXTERNAL:	LPDR NSIC	1 1	1 1	NRC PDR	1	·1	S

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!



Docket No. 50-397

Washington Public Power Supply System P. O. Box 968 3000 George Washington Way Richland, Washington 99352

Attention: Mr. G. C. Sorensen, Manager

Regulatory Programs

Gentlemen:

SUBJECT: NRC INSPECTION OF WNP-2

This refers to the routine on site inspection conducted by Mr. G. Cicotte of this office on February 21-24, 1989, of activities authorized by NRC License No. NPF-21, and to the discussion of our findings held by Mr. Cicotte with Mr. A. Oxsen, Mr. C. Powers and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements as set forth in the Notice of Violation, enclosed herewith as Appendix A.

Your response to this Notice is to be submitted in accordance with the provisions of 10 CFR 2.201 as stated in Appendix A, Notice of Violation.

This violation involves the failure to maintain conspicuous posting of a caution radiation area sign. Similar examples of failure to maintain radiation area postings have been previously brought to your attention by our inspectors during this last year. In view of your planned April 1989 refueling outage we expect your response to the violation will describe more effective corrective actions.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

8904040165 890316 PDR ADOCK 05000397 Q PDC TESS

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,

Gregory (P. Yuhas, Chief Emergency Preparedness and

Radiological Protection Branch

Enclosures:

Appendix A (Notice of Violation)

2. Inspection Report No. 50-397/89-09

cc w/enclosures:

C. M. Powers, WPPSS

A. G. Hosler, WPPSS

G. D. Bouchey, WPPSS

G. E. Doupe, Esq., WPPSS

A. L. Oxsen, WPPSS

N. S. Reynolds, Esq., BCP&R

T. Strong, DSHS

State of Washington

bcc w/enclosure:

Project Inspector

Resident Inspector

docket file

G. Cook

B. Faulkenberry

J. Martin

T. Foley, NRR

bcc w/o enclosure:

J. Zollicoffer

M. Smith

REGION V
GRCicotte AJohnson GPYuhas
3/14/89 3/16/89
3/16/89

REQUEST COPY] REQUEST COPY] REQUEST COPY YES) / NO] YES / NO] (YES) / NO

SEND TO PDR YES / NO