

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8905010192 DOC. DATE: 89/04/17 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME AUTHOR AFFILIATION
 HUEY, F.R. Region 5, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 SORENSEN, G.C. Washington Public Power Supply System

SUBJECT: Forwards Insp Rept 50-397/89-08 on 890208-0314. Violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+13
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL	ID CODE/NAME		LTTR	ENCL
	PD5 PD		1	1	SAMWORTH, R		1	1
INTERNAL:	ACRS		2	2	AEOD		1	1
	AEOD/DEIIB		1	1	DEDRO		1	1
	NRR SHANKMAN, S		1	1	NRR/DEST DIR		1	1
	NRR/DLPQ/PEB 11		1	1	NRR/DLPQ/QAB 10		1	1
	NRR/DOEA DIR 11		1	1	NRR/DREP/EPB 10		1	1
	NRR/DREP/RPB 10		2	2	NRR/DRIS DIR 9A		1	1
	NRR/PMAS/ILRB12		1	1	NUDOCS-ABSTRACT		1	1
	OE LIEBERMAN, J		1	1	OGC/HDS2		1	1
	REG FILE 02		1	1	RGN5 FILE 01		1	1
EXTERNAL:	LPDR		1	1	NRC PDR		1	1
	NSIC		1	1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

R
I
D
S
/
A
D
D
S
/
A
D
D
S

APR 17 1989

Docket No. 50-397

Washington Public Power Supply System
P. O. Box 968
Richland, Washington 99352

Attention: Mr. G. C. Sorensen
Manager, Regulatory Programs

Gentlemen:

Subject: NRC Inspection

This refers to the inspection conducted by Messrs. C. J. Bosted and R. C. Sorensen of this office on February 8 - March 14, 1989 of activities authorized by NRC Operating License No. NPF-21, and to the discussions of findings held by the inspectors with Mr. J. Baker and other members of the Supply System staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel and observations by the inspectors.

Based on the results of this inspection, a Severity Level V violation was identified as discussed in paragraph 13 of the enclosed report. Pursuant to 10 CFR Part 2, Appendix C, a Notice of Violation was not issued for this violation. The effectiveness of your corrective action will be examined during a future inspection.

In accordance with 10 CFR 2.790 (a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original signed
F. R. Huey, Acting Chief
Reactor Projects Branch

Enclosure:
Inspection Report No. 50-397/89-08

8905010192 890417
PDR ADOCK 05000397
Q PDC

IEU

APR 17 1989

cc: A. L. Oxsen, Assistant Managing Director for Operations
 G. D. Bouchey, WPPSS Director, Assurance & Licensing
 C. M. Powers, WNP-2 Plant Manager
 A. G. Hosler, WNP-2 Licensing Manager
 G. E. Doupe, Esq.
 N. S. Reynolds, Debevois, Cook, Purcell & Reynolds
 State of Washington

bcc w/copy of enclosure:

Docket File
 Project Inspector
 Resident Inspector
 G. Cook
 B. Faulkenberry
 J. Martin
 A. Johnson
 R. Nease, NRR

bcc w/o enclosure:

M. Smith
 LFMB

[Signature]
 REGINA V
 CSorensen
 for 4/11/89

[Signature]
 CBosted
 for 4/11/89

[Signature]
 PJohnson
 4/11/89

[Signature]
 RHuey
 4/17/89

REQUEST COPY YES / NO	REQUEST COPY YES / NO	REQUEST COPY YES / NO	REQUEST COPY YES / NO
--------------------------	--------------------------	--------------------------	--------------------------

SEND TO PDR YES / NO

E

