

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9112260066 DOC. DATE: 91/12/18 NOTARIZED: NO DOCKET #
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH. NAME AUTHOR AFFILIATION
 SORENSEN, G.C. Washington Public Power Supply System
 RECIPIENT AFFILIATION
 RECIP. NAME Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Inservice Insp Summary Rept for Refueling Outage
 RF91A."

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 5 SIZE: 1+250
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES: *See Reports*

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL
	PD5 LA		1	0	PD5 PD		1	1
	ENG, P.L.		2	2				
INTERNAL:	ACRS		6	6	NRR/DET/ECMB 9H		1	1
	NRR/DET/EMEB 7E		1	1	NUDOCS-ABSTRACT		1	1
	OC/LEMB		1	0	OGC/HDS1		1	0
	<u>REG' FILE</u> 01		1	1	RES/DSIR/EIB		1	1
EXTERNAL:	EG&G BROWN, B		1	1	EG&G RANSOME, C		1	1
	NRC PDR		1	1	NSIC		1	1


NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 21 ENCL ~~18~~
 13

MA [Signature]

R
I
D
S
/
A
D
D
S
/
A
D
D
S



WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

December 18, 1991
G02-91-229

Docket No. 50-397

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Gentlemen:

Subject: NUCLEAR PLANT NO. 2, OPERATING LICENSE NPF-21
INSERVICE INSPECTION SUMMARY REPORT NIS-1,
NIS-2, OWNER'S REPORTS

Reference: Letter, G02-90-185, GC Sorensen (SS) to NRC,
same subject, dated November 2, 1990

In accordance with the requirements of 10CFR 50.55a(g) and IWA-6230 of ASME Section XI, as previously agreed, the Supply System hereby submits five (5) copies of the WNP-2 Inservice Inspection (ISI) Summary Report for the Spring 1991 refueling outage. Included in the Summary Report are the NIS-1 Owner's Data Report for inservice inspections performed during the Spring 1991 refueling outage, and NIS-2 Owner's Reports on repair or replacement completed since the filing of the last ISI Summary Report (see reference).

Very truly yours,

Alan Sorensen

G. C. Sorensen, Manager
Regulatory Programs

ME/bk
Attachments

cc: JB Martin - NRC RV
NS Reynolds - Winston & Strawn
PL Eng - NRC
DL Williams - BPA/399
NRC Site Inspector - 901A

240011
9112260066 911218
PDR ADOCK 05000397
Q PDR

*A047
1/8*