

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

1450 MARIA LANE WALNUT CREEK, CALIFORNIA 94596-5368

JAN - 3 1992

Docket No. 50-397

Washington Public Power Supply System P. O. Box 968 3000 George Washington Way Richland, Washington 99352

Attention:

Mr. G. C. Sorenson, Manager

Regulatory Programs

Subject:

NRC INSPECTION OF WNP-2

This letter refers to the routine inspection conducted by Messrs. R. Bocanegra and L. Carson of this office on October 28 through November 1, 1991, and December 2-5, 1991, of activities authorized by NRC License No. NPF-21, and to the discussion of our findings with Mr. J. Baker and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

No violations of NRC requirements were identified within the scope of this inspection. A weakness in implementation of your Corporate Chemistry Committee's oversight of chemistry activities was noted. This concern merits your attention.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.


Sincerely,

Gregory P. Yuhas, Phief

Reactor Radiological Protection Branch

Enclosure:

Inspection Report No. 50-397/91-40



bcc w/enclosures
Docket File
Mr. G. Cook
Mr. B. Faulkenberry
Mr. J. Martin
Resident Inspector
Project Inspector
State of Washington


bcc w/o enclosures
J. Zollicoffer
M. Smith

Region V/carol

locRBocanegra by LCarson
1/3/92 1/3/92

for GYuhas 1/3/97

[REQUEST COPY] [REQUEST COPY] [REQUEST COPY] [SEND TO PDR [YES NO] [YES NO] [YES NO]



.