ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM								
. REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)								
ACCESSION NBR:9205130060 DOC.DATE: 92/04/21 NOTARIZED: NO DOCKET # FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397 AUTH.NAME AUTHOR AFFILIATION SORENSEN,G.C. Washington Public Power Supply System RECIP.NAME RECIPIENT AFFILIATION								
								R
SUBJECT: Forwards "1991 Annual Environ Operating Rept." One NPDES permit violation occurred on 920521 re pH exceeding 9.0 for								Ι
one h,reaching max of 10.1.No design or operational changes or tests in 1991 involved unreviewed environ questions.								D
DISTRIBUTION CODE: IE25D COPIES RECEIVED:LTR $($ ENCL $($ SIZE: $(+)$ TITLE: Environmental Monitoring Rept (per Tech Specs)								S
NOTES:								/
·	RECIPIENT ID CODE/NAME PD5 LA DEAN,W.	COPJ LTTF 3 1	IES RENCL 3 1	RECIPIENT ID CODE/NAME PD5 PD	COP LTTR 1	IES ENCL 1		A D D
INTERNAL:	REG_FILE 0	1 1 2 1	1 1 1	NRR/DREP/PRPB11 RGN5 DRSS/RPB		2 1		S
EXTERNAL:	EG&G SIMPSON, F	2	2	NRC PDR	1.	1		
							v • 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 14

R

Ι

D

Ś

1

Α

Ď

D

S

÷.

## 

۹.

•

. .

.

**5** =

WASHINGTON PUBLIC FOWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Mail Station P1-137 Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2 1991 ANNUAL ENVIRONMENTAL OPERATING REPORT

This letter is submitted per reporting requirements of Section 5.4.1 of the WNP-2 Environmental Protection Plan (EPP)( Appendix B to Facility Operating License NPF-21).

A summary of the effluent data reported to the State of Washington on the monthly discharge monitoring reports is attached. One NPDES permit violation occurred in 1991. On May 21 the pH exceeded the limit of 9.0 for one hour, reaching a maximum of 10.1. The incident was reported to the Energy Facility Site Evaluation Council which subsequently issued a Notice of Violation (with \$1000 penalty) on August 26. No environmental impact was observed or alleged to have been attributable to the incident.

No design or operational changes or tests in 1991 involved an unreviewed environmental question. Also, no non-routine reports (within the context of EPP Section 5.4.2) were required for 1991.

Please contact us if you require additional information on this report.

9205130060 92042

ADOCK 05000397

G.C. Sorensen, Manager Regulatory Programs (MD-280)

Attachment: Table of 1991 effluent data

cc: RC Sorensen, NRC Resident (901A) JJ Zeller, EFSEC JB Martin, NRC Region V WM Dean, NRC NRR

PDR

- 1. E

.

• -

. .

. .

.

· · · · ·