	ę		CATE	EGORY 1		
\$ 2		REGULATORY	ĮNFORMĄTION	UDISTRIBUTION SYSTE	EM (RIDS)	
FACIL:5	0-397 W Ame: R.Pi	PPSS Nuclea AUTHOR B&G Manu RECIPIE	r Project, U AFFILIATION facturing Cc NT AFFILIATI		Public Powe (DOCKET # 05000397
SUBJECT	Cardin hardno	nal Industr: ess.Failed :	ial Products lots & any r	pplied to WPPSS by ,LP (CIP) having no emaining product fo apped & removed fro	onconforming ound to have	. C A
DISTRIB TITLE:	UTION CO	=	COPIES RECE	$ived: ltr \perp encl \bigcirc$	-	T
NOTES:		-		· · · ·		E
-		IPIENT	COPIES	RECIPIENT	COPIES	G
	PD4-2 1	DDE/NAME PD	LTTR ENCL	ID CODE/NAME COLBURN,T	LTTR ENCL	O R
INTERNAL:	NRR/DRI RES/DSI	PM/PECB	1 1 2 2 1 1	NRR/DRCH/HQMB PDR WARD, M. RGN1		Y
	RGN2 RGN4	21 K N		RGN3	1	1
EXTERNAL:	INPO RI NRC PDI		1	NOAC SILVER,E NUDOCS FULL TXT	1 1	D
			·			0
						C
		,				υ
				u N		M E
						N
						т
			• •	,		
,			н ^Ф			
PLEAS	SE HELP U OWFN 5D-	5(EXT. 415-208	STE! CONTACT T	HE DOCUMENT CONTROL DESK E YOUR NAME FROM 人 T NEED!	THIS DOCUMEN	
	•				SEN SCANA,	/T
			· · ·			:D "

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL

ŧ

.

h.

5. E

, , ,

.

•

•



Home Office: 3067 Unionville Pike P.O. 80x 904 Hattleid, PA 19440-0904 215-822-1925

May 8, 1996

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

Reference: 10 CFR, Part 21 Courtesy Notification

To Whom It May Concern:

This letter provides to the Nuclear Regulatory Commission a courtesy notification as referenced by 10 CFR Part 21, paragraph 21.21, (4).

Washington Public Power Supply System ("WPPSS") formally informed ACCUTECH, a division of B&G Manufacturing Co., Inc. ("B&G"), of capscrews recently found to have nonconforming hardness. The trace code TS-7 showed that these capscrews were supplied to WPPSS by the now defunct Cardinal Industrial Products, L.P. ("CIP") during February, 1994.

On July 10, 1995, B&G purchased the name and certain other assets from CIP, a limited partnership that had been formed and operated in Nevada. B&G began its own nuclear fastener business at the same Nevada site, and temporarily used the "Cardinal Industrial Products" name before officially adopting the trade name of ACCUTECH in December, 1995.

Although B&G is not bound to take formal action under 10 CFR Part 21, WPPSS's notification prompted us to investigate not only the capscrews in question but other inventory that B&G acquired from CIP. We performed hardness tests on any and all inventory still on site that had been heat treated by CIP. Failures were noted in the following two lots: (1) $3/8^{\circ}$ - $16 \times 1^{\circ}$ capscrews, trace code TS-7: 16 pieces failed out of 1,086 pieces tested (note that WPPSS's test results were 2 failed pieces out of 98 tested); (2) $1^{\circ} \times 4^{\circ}$ capscrew blanks, trace code K7: 6 pieces failed out of 71 pieces tested.

We believe that the nonconforming hardness was the result of insufficient heat treating performed by CIP at the Nevada site. Therefore, we have scrapped and removed from the premises not only the failed lots, but any remaining product found to have been heat treated by CIP.

9605150136 960508 PDR . 05000397 ADOCK PDR Suppliers of: Bolts - Nuts - Studs - Threaded Rods - Machined Specials Service Centers: 6870 N. Fathom St. 10231 General Dr. 4660 Pine Timbers 3873 W. Oquendo Portland, OR 97217 Orlando, FL 32824 Houston, IX 77041 Las Vegas, NV 89118 503-286-6601 407-857-5858 215-822-1925 702-739-1966

Page 2 of 2

Even though the obligation for statutory notifications remains with CIP, as a courtesy B&G is notifying the NRC of the situation. In addition, based upon records acquired from CIP, B&G is sending courtesy notifications to customers who were shipped product from these two lots by Cardinal Industrial Products, L.P.

٢

Sincerely yours,

Roy P. Reindl Branch Manager, Nevada

. 6 - 4

• • •

,