

.88 JUN 13 P1:33

8664146310



Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

161-01056-EEVB/RAB
May 26, 1988

Docket Nos. STN 50-530

Document Control Desk
U. S. Nuclear Regulatory Commission
Mail Station P1-137
Washington, D.C. 20555

Dear Sir:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 3
Loose Part Detection Program Report
File: 88-056-026

Enclosed is the Loose Part Detection Program Report as required by Regulatory Guide 1.133.

If you should have any questions, please contact Mr. Richard A. Bernier of my staff at (602) 371-4295.

Very truly yours,

E. E. Van Brunt, Jr.
Executive Vice President
Project Director

EEVB/RAB/dlm

Enclosure

cc: J. R. Martin
G. W. Knighton
T. J. Polich
M. J. Davis
A. C. Gehr

*Drawings
to: Reg Files*

*A001
11/1*

8806130011 880526
PDR ADOCK 05000530
P DCD

