

Docket Nos. 50-528, 50-529 and 50-530

> Mr. William F. Conway Executive Vice President, Nuclear Arizona Public Service Company Post Office Box 53999 Phoenix, Arizona 85072-3999

Dear Mr. Conway:

SUBJECT: CONTAINMENT HYDROGEN ANALYZERS PALO VERDE NUCLEAR GENERATING STATION

This is in response to your letter of June 26, 1992, in which you reported improvements in containment hydrogen analyzer performance at Palo Verde. You indicate that as a result of improved maintenance, the hydrogen analyzers now consistently meet the requirement to provide continuous indication of hydrogen concentration within 30 minutes of activation. Therefore, you have cancelled your earlier plan to replace them.

Since these monitors now fully meet the response time characteristics called for in NUREG 0737, this is an acceptable revision to our Safety Evaluation of October 10, 1991.


> Sincerely, Original signed by:

Charles M. Trammell, Senior Project Manager Project Directorate V Division of Reactor Projects III/IV/V Office of Nuclear Reactor Regulation

cc: See next page

DISTRIBUTION:			
(Docket File	NRC & Local PDRs	PDV r/f	BBoger
MVirgilio	TQuay	DFoster	CTrammell
CMcCracken	OGC (15B18)	ACRS (10)(P315)	PDV p/f
KPerkins, RV			••

D:PDV pt LA:PDV4 OFC PM: POV : SPLB CTrammell : CTDompson : NAME : CMcCracken : TOuay DFoster /92 8 13 192 8/1/92 : √<u>√</u>/92 DATE **PVHYDRO.LTR** OFFICIAL RECORD COPY **DOCUEMNT NAME:** 



mec file center cop



а 4

, <sup>1</sup> 14,

^, ♦., ∎ ¥

ż





UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

August 4, 1992

Docket Nos. 50-528, 50-529 and 50-530

> Mr. William F. Conway Executive Vice President, Nuclear Arizona Public Service Company Post Office Box 53999 Phoenix, Arizona 85072-3999

Dear Mr. Conway:

SUBJECT: CONTAINMENT HYDROGEN ANALYZERS PALO VERDE NUCLEAR GENERATING STATION

This is in response to your letter of June 26, 1992, in which you reported improvements in containment hydrogen analyzer performance at Palo Verde. You indicate that as a result of improved maintenance, the hydrogen analyzers now consistently meet the requirement to provide continuous indication of hydrogen concentration within 30 minutes of activation. Therefore, you have cancelled your earlier plan to replace them.

Since these monitors now fully meet the response time characteristics called for in NUREG 0737, this is an acceptable revision to our Safety Evaluation of October 10, 1991.

Sincerely,

ales M. Traimell

Charles M. Trammell, Senior Project Manager Project Directorate V Division of Reactor Projects III/IV/V Office of Nuclear Reactor Regulation

cc: See next page



.

4

.

,

. м .

н .

•

Mr. William F. Conway Arizona Public Service Company

## cc:

Nancy C. Loftin, Esq. Corporate Secretary & Counsel Arizona Public Service Company P. O. Box 53999, Mail Station 9068 Phoenix, Arizona 85072-3999

James A. Beoletto, Esq. Southern California Edison Company P. O. Box 800 Rosemead, California 91770

Senior Resident Inspector U.S. Nuclear Regulatory Commission HC-03 Box 293-NR Buckeye, Arizona 85326

Regional Administrator, Region V U. S. Nuclear Regulatory Commission 1450 Maria Lane Suite 210 Walnut Creek, California 94596

Mr. Charles B. Brinkman, Manager Washington Nuclear Operations ABB Combustion Engineering Nuclear Power 12300 Twinbrook Parkway, Suite 330 Rockville, Maryland 20852

Mr. William A. Wright, Acting Director Arizona Radiation Regulatory Agency 4814 South 40 Street Phoenix, Arizona 85040

Chairman Maricopa County Board of Supervisors 111 South Third Avenue Phoenix, Arizona 85003 Palo Verde

Jack R. Newman, Esq. Newman & Holtzinger, P.C. 1615 L Street, N.W., Suite 1000 Washington, D.C. 20036

Curtis Hoskins Executive Vice President and Chief Operating Officer Palo Verde Services 2025 N. 3rd Street, Suite 220 Phoenix, Arizona 85004

Roy P. Lessey, Jr., Esq. Bradley W. Jones, Esq. Arkin, Gump, Strauss, Hauer and Feld El Paso Electric Company 1333 New Hampshire Ave., Suite 400 Washington, D.C. 20036

, ł ч

5