ACCELERATED DOCUMENT DISTRIBUTION SYSTEM REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

4	(,	•		•		
FACIU: ST ST ST	TN-50-528 Palo Verd TN-50-529 Palo Verd	e Nuclear Sta e Nuclear Sta e Nuclear Sta	2/12/15 NOTARIZED: ation, Unit 1, Ariz ation, Unit 2, Ariz ation, Unit 3, Ariz	ona Publi ona Publi	05000529	-
CONWAY, W.F. Arizona Public Service Co. (formerly Arizona Nuclear Power						RÍ
RECIP.		T AFFILIATION t Control Bra	N anch (Document Cont	rol Desk)		I
SUBJECT: Submits status of implementations of 10CFR50.62, ATWS rule.						D
DISTRIBUTION CODE: A055D COPIES RECEIVED:LTR ENCL O SIZE: 2						_
TITLE: OR/Licensing Submittal: Salem ATWS Events GL-83-28						S
NOTES:STANDARDIZED PLANT Standardized plant.					05000528 05000529	1
Standardized plant.					05000530	Α
	,					
	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		D
	PD5 LA TRAMMELL,C	$\begin{array}{ccc} 1 & 0 \\ 2 & 2 \end{array}$	PD5 PD	1 1		D
INTERNAL:	ACRS		NRR/DEST/ESB 8D	1 1		S
	NRR/DLPQ/LPEB10 NRR/DST/SICB8H3	6 6 1 0 1 1 1 0	NRR/DOEA/OGCB11 NRR/DST/SPLB 8D	1		
	OC/LEMB	1 0	OGC/HDS1	1 d		1
	REG FILE 01	1 }	RES/DSIR/EIB	1 1	-	
EXTERNAL:	NRC PDR	1 1	NSIC	1 1		
		i		•		

NOTE TO ALL "RIDS" RECIPIENTS:

R

I

D

S


D

D

S

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

ENCL TOTAL NUMBER OF COPIES REQUIRED: LTTR 21



Arizona Públic Service Company

P.O. BOX 53999 • PHOENIX, ARIZONA 85072-3999

WILLIAM F. CONWAY EXECUTIVE VICE PRESIDENT

102-02376-WFC/TRB/RAB December 15, 1992

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Station P1-37 Washington, DC 20555

Dear Sirs:

Subject:

Palo Verde Nuclear Generating Station (PVNGS)

Units 1, 2, and 3

Docket Nos. STN 50-528/529/530

Status of Implementations of 10 CFR 50.62, ATWS Rule

File: 92-056-026

Arizona Public Service Company (APS) has completed the necessary modifications to implement 10 CFR 50.62(c)(1) and (2) in the three PVNGS units.

The Diverse Scram System (DSS) modifications were completed as follows:

Unit 1 - prior to restart from the third refueling outage in May 1992.

Unit 2 - prior to restart from the second refueling outage in July 1990.

Unit 3 - prior to restart from the second refueling outage in June 1991.

The Diverse Auxiliary Feedwater Actuation System (DAFAS) modifications were completed as follows:

Unit 1 - prior to restart from the third refueling outage in May 1992.


Unit 2 - prior to restart from the third refueling outage in January 1992.

Unit 3 - prior to restart from the third refueling outage in November 1992.

The Diverse Turbine Trip requirements were met when the DSS modifications were

290001

9212290211 921215 PDR ADDCK 05000528 AD55 10



U. S. Nuclear Regulatory Commission

ATTN: Document Control Desk

Status of Implementations of 10 CFR 50.62

Page 2

Please call Richard A. Bernier at (602) 393-5882 if you have any questions.

Sincerely.

WFC/TRB/RAB/pmm

cc:

J. B. Martin

J. A. Sloan

C. M. Trammell

