



# ECOLOGY SERVICES, INC

9135 Guilford Road, Suite 200  
Columbia, Maryland 21046  
Tel (301) 362-6700  
Fax (301) 490-0172

October 24, 2017

Director of FSME  
Attn: GLTS  
US Nuclear Regulatory Commission  
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on October 24, 2017 we transferred the self-luminous exit signs listed on the attached spreadsheet(s) to SRB Technologies, Inc, Winston-Salem, NC, license 034-0534-2. As required, for each sign listed on the spreadsheet(s), we include the name of the manufacturer, model number, and serial number. The original owner/place of installation was Cotter Corporation-Cannon City Milling Facility, Cannon City, CO.

If you should have any questions, please contact Greg Keck, Ecology Services, Inc. at 301-362-6700

Sincerely,

Greg Keck  
ESI Operations Manager

Encl.

*[Faint, illegible text, likely bleed-through from the reverse side of the page]*

## COTTER CORP

		Manufacturer	Model	Serial Number	Mnfc. Date	Original Curies	Curies Oct-17
Carton 1	1	American Atomics	40113	18278	Mar-78	21	2.3
	2	American Atomics	40113	18273	Mar-78	21	2.3
	3	American Atomics	40113	18276	Mar-78	21	2.3
	4	American Atomics	40113	not legible	Mar-78	21	2.3
	5	American Atomics	40113	18321	Mar-78	21	2.3
	6	American Atomics	40113	18317	Mar-78	21	2.3
	7	American Atomics	40113	18328	Mar-78	21	2.3
	8	American Atomics	40113	18293	Mar-78	21	2.3
	9	American Atomics	40113	not legible	Mar-78	21	2.3
	10	American Atomics	40113	not legible	Mar-78	21	2.3
Carton 2	11	American Atomics	40113	18287	Mar-78	21	2.3
	12	American Atomics	40113	18331	Mar-78	21	2.3
	13	American Atomics	40113	18334	Mar-78	21	2.3
	14	American Atomics	40113	18315	Mar-78	21	2.3
	15	American Atomics	40113	18277	Mar-78	21	2.3
	16	American Atomics	40113	18292	Mar-78	21	2.3
	17	American Atomics	40113	not legible	Mar-78	21	2.3
	18	American Atomics	40113	18294	Mar-78	21	2.3
	19	American Atomics	40113	18304	Mar-78	21	2.3
	20	Isolite	880-1265	C-28103	Aug-82	22.5	3.17
Carton 3	21	American Atomics	40113	18306	Mar-78	21	2.3
	22	American Atomics	40113	18298	Mar-78	21	2.3
	23	American Atomics	40113	18285	Mar-78	21	2.3
	24	American Atomics	40113	18302	Mar-78	21	2.3
	25	American Atomics	40113	18333	Mar-78	21	2.3
	26	American Atomics	40113	18281	Mar-78	21	2.3
	27	American Atomics	40113	18301	Mar-78	21	2.3
	28	American Atomics	40113	18325	Mar-78	21	2.3
	29	American Atomics	40113	18324	Mar-78	21	2.3
	30	American Atomics	40113	18303	Mar-78	21	2.3
Carton 4	31	American Atomics	40113	18299	Mar-78	21	2.3
	32	American Atomics	40113	18270	Mar-78	21	2.3
	33	American Atomics	40113	18272	Mar-78	21	2.3
	34	American Atomics	40113	18271	Mar-78	21	2.3
	35	American Atomics	40113	18314	Mar-78	21	2.3
	36	American Atomics	40113	18307	Mar-78	21	2.3
	37	American Atomics	40113	18332	Mar-78	21	2.3
	38	American Atomics	40113	18284	Mar-78	21	2.3
	39	American Atomics	40113	18295	Mar-78	21	2.3
	40	American Atomics	40113	18330	Mar-78	21	2.3
Carton 5	41	American Atomics	40113	18327	Mar-78	21	2.3
	42	American Atomics	40113	19325	Jun-78	21	2.3
	43	American Atomics	40113	18313	Mar-78	21	2.3
	44	American Atomics	40113	18282	Mar-78	21	2.3
	45	American Atomics	40113	18268	Mar-78	21	2.3
	46	American Atomics	40113	18329	Mar-78	21	2.3

	Manufacturer	Model	Serial Number	Mnfc. Date	Original Curies	Curies Oct-17
	American Atomics	40113	not legible	Mar-78	21	2.3
	American Atomics	40113	18279	Mar-78	21	2.3
	American Atomics	40113	18297	Mar-78	21	2.3
	American Atomics	40113	18300	Mar-78	21	2.3
carton 6	American Atomics	40113	18291	Mar-78	21	2.3
	American Atomics	40113	19326	Jun-78	21	2.3
	Shield Source	C3	P8974	Dec-00	7.5	2.9
	Shield Source	C3	P8975	Dec-00	7.5	2.9
	Shield Source	C3	P8979	Dec-00	7.5	2.9
	Shield Source	C3	P8976	Dec-00	7.5	2.9
	Shield Source	C3	R2772	May-01	7.5	3
	Shield Source	C3	P8977	Dec-00	7.5	2.9
	Shield Source	C3	P8980	Dec-00	7.5	2.9
	Shield Source	C3	R6553	Sep-01	7.5	3.05
Carton 7	American Atomics	40113	18269	Mar-78	21	2.3
	American Atomics	40113	18322	Mar-78	21	2.3
	American Atomics	40113	18312	Mar-78	21	2.3
	American Atomics	40113	18311	Mar-78	21	2.3
	American Atomics	40113	18326	Mar-78	21	2.3
	American Atomics	40113	18308	Mar-78	21	2.3
	American Atomics	40113	18267	Mar-78	21	2.3
	American Atomics	40113	18266	Mar-78	21	2.3
	American Atomics	40113	18316	Mar-78	21	2.3
	American Atomics	40113	18275	Mar-78	21	2.3
Carton 8	American Atomics	40113	18305	Mar-78	21	2.3
	American Atomics	40113	18323	Mar-78	21	2.3
	American Atomics	40113	18274	Mar-78	21	2.3
	American Atomics	40113	18320	Mar-78	21	2.3
	American Atomics	40113	18288	Mar-78	21	2.3
	American Atomics	40113	18269	Mar-78	21	2.3
	Shield Source	C3	P8978	Dec-00	7.5	2.9
	Isolite	880-1265	C28105	Aug-82	22.5	3.17
	Isolite	880-1265	not legible	not legible	not legible	3.17

189.96