# CATEGORY 2

11


6.

. •

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

	REGULATORI	INION	MALION	DISTRIBUTION SIST.		3)					
STN-50-	528 Palo Verd 529 Palo Verd 530 Palo Verd AUTHOR A Region 4 RECIPIEN	e Nuc e Nuc FFILIA (Post T AFF	lear S lear S lear S ATION 82020 ILIATIO		izona P izona P izona P	ubli ubli	05000529 05000530 ,				
	arda inan ran	ha 50.	- 5 2 9 / 0 -		-			C			
				7-10,50-529/97-10 a violations noted.	X			A			
DISTRIBUTION CODE: 1E35F COPIES RECEIVED:LTR $1$ ENCL $1$ SIZE: $4+23$											
TITLE: Emergency Preparedness-Appraisal/Confirmatory Action Ltr/Exercise Rep											
NOTES:STANDARDIZED PLANT 05000528											
Standardized plant. 05000529 Standardized plant. 05000530											
	E							0			
	CIPIENT	COPII		RECIPIENT	COP	-		-			
ID ( PD4-2	CODE/NAME PD	LTTR l	ENCL 1	ID CODE/NAME THOMAS,K	LTTR 1	ENCL 1		R			
INTERNAL: FILE		1	1	NRR)DISP/PIPB	1	•		Y			
NRR7DI	RPM/PERB	1	1	OE DIR	1	1 1		~			
RGN4	FILE 01	1	1				•	2			
ERNAL: NOAC		1	1	NRC PDR	1	1					
								D			
1						`	÷	0			
	,		•	٤		•	·	C			
								π			
		,	,								
							•	M			
ŧ			1					E			
· · ·	e			·				N			
								T			
				•							
						1					
	ч				,						
1				1							
PLEASE HELP US OR REDUCE THE 1	LIDS" RECIPIENTS TO REDUCE WASTE. NUMBER OF COPIES EXTENSION 415-20	. TO HAV RECEIVE	ve your 1 Ed by you	NAME OR ORGANIZATION REN J OR YOUR ORGANIZATION,	OVED FRO	M DISTR THE DOC	IBUTION LIS UMENT CONTR	ts Ol			
TOTAL NUMBER (	OF COPIES REQ	UIRED:	LTTR	9 ENCL 9		•					

TOTAL NUMBER OF COPIES REQUIRED: LTTR 9 ENCL 9



۲

.

·

. . .



## UNITED STATES NUCLEAR REGULATORY COMMISSION

**REGION IV** 

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

June 24, 1997

James M. Levine, Senior Vice President, Nuclear Arizona Public Service Company P.O. Box 53999 Phoenix, Arizona 85072-3999

## SUBJECT: NRC INSPECTION REPORT 50-528/97-10; 50-529/97-10; 50-530/97-10


Dear Mr. Levine:

An NRC inspection was conducted May 20-23, 1997, at your Palo Verde Nuclear Generating Station, Units 1, 2, and 3, reactor facilities. The enclosed report presents the scope and results of that inspection. Followup conversations were held on June 11-13, 1997, to discuss additional information that became available after the May 23, 1997, exit meeting and a change in the characterization of one issue involving continuous personnel accountability.

The inspection included implementation of your emergency plan and procedures during your biennial emergency preparedness exercise. Overall, the performance during the biennial exercise was good; however, two exercise weaknesses and a number of other performance issues, which detacted from the overall effectiveness, were identified. The two exercise weaknesses pertained to the failure to recognize and declare the notification of unusual event and the failure to make required offsite agency notifications.

Exercise weaknesses, according to 10 CFR Part 50, Appendix E.IV.F.2.g, are inspection findings that need to be corrected by the licensee. Therefore, you are requested to provide this office with a description of your corrective measures and your schedule for completing these actions within 30 days after receipt of this letter.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.



Arizona Public Service Company

-4-

E-Mail report to T. Boyce (THB) E-Mail report to NRR Event Tracking System (IPAS) E-Mail report to Document Control Desk (DOCDESK)

bcc to DCD (IE35)

bcc distrib. by RIV:

Regional Administrator DRP Director Branch Chief (DRP/F, WCFO) Senior Project Inspector (DRP/F, WCFO) Branch Chief (DRP/TSS) WCFO File Resident Inspector DRS-PSB MIS System RIV File M. Hammond (PAO, WCFO)

## DOCUMENT NAME: R:\\_PV\PV710RP.GMG

To receive copy of document, indicate in box: "C" = Copy without enclosures, "E" = Copy with enclosures "N" = No copy

p		- V - AGAN		
RIV:SEPA:PSB E	RS:PSB	RE:DRP N	NRR N	NRR N
GMGood:Imb	5 THAndrews TH	SFreeman	THESSIG PErroi	SKlementowicz
06/3/97	06/1797 J	0618/97 Bor Entail	06/10/97	06/1/97 Per-Eng
C:PSB	D:DRP	D:DRSZ		
BMurray D	TPGwym	ATHANdll	1	
061897	06/1971	061197	06/ /97	06/ /97
		LAL BECORD CO		

OFFICIAL RECORD COPY

### Arizona Public Service Company

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

-2-

Sincerely, well III, Director

Division of Reactor Safety

Docket Nos.: 50-528; 50-529; 50-530 License Nos.: NPF-41; NPF-51; NPF-74

Enclosure: NRC Inspection Report 50-528/97-10; 50-529/97-10; 50-530/97-10

cc w/enclosure: Mr. Steve Olea Arizona Corporation Commission 1200 W. Washington Street Phoenix, Arizona 85007

Douglas K. Porter, Senior Counsel Southern California Edison Company Law Department, Generation Resources P.O. Box 800 Rosemead, California 91770

Chairman Maricopa County Board of Supervisors 301 W. Jefferson, 10th Floor Phoenix, Arizona 85003

Aubrey V. Godwin, Director Arizona Radiation Regulatory Agency 4814 South 40 Street Phoenix, Arizona 85040

Angela K. Krainik, Manager Nuclear Licensing Arizona Public Service Company P.O. Box 52034 Phoenix, Arizona 85072-2034





#### Arizona Public Service Company

John C. Horne, Vice President Power Supply El Paso Electric Company 2025 N. Third Street, Suite 220 Phoenix, Arizona 85004

Terry Bassham, Esq. General Counsel El Paso Electric Company 123 W. Mills El Paso, Texas 79901

Mr. Robert Burt Los Angeles Department of Water & Power Southern California Public Power Authority 111 North Hope Street, Room 1255-B Los Angeles, California 90051

Mr. David Summers Public Service Company of New Mexico 414 Silver SW, #0604 Albuquerque, New Mexico 87102

Mr. Brian Katz Southern California Edison Company 14300 Mesa Road, Drop D41-SONGS San Clemente, California 92672

Mr. Robert Henry Salt River Project 6504 East Thomas Road Scottsdale, Arizona 85251

Training, Exercise & Evaluation Branch Chief FEMA Region IX Building 105 Presidio of San Francisco San Francisco, California 94129 -3-