

CATEGORY 1

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9707150356 DOC.DATE: 97/07/07 NOTARIZED: NO DOCKET #
 FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528
 AUTH.NAME AUTHOR AFFILIATION
 OVERBECK,G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 97-002-00, reporting violation of TS due to missing performance of SR for core protection calculators.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: STANDARDIZED PLANT

05000528


	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME	PD4-2 PD	LTR	ENCL		ID CODE/NAME	LTR	ENCL	
			1	1	THOMAS, K	1	1		
INTERNAL:	ACRS		1	1	AEOD/SPD/RAB	2	2		
	AEOD/SPD/RRAB		1	1	<u>FILE CENTER</u>	1	1		
	NRR/DE/ECGB		1	1	NRR/DE/EELB	1	1		
	NRR/DE/EMEB		1	1	NRR/DRCH/HHFB	1	1		
	NRR/DRCH/HICB		1	1	NRR/DRCH/HOLB	1	1		
	NRR/DRCH/HQMB		1	1	NRR/DRPM/PECB	1	1		
	NRR/DSSA/SPLB		1	1	NRR/DSSA/SRXB	1	1		
	RES/DET/EIB		1	1	RGN4 FILE 01	1	1		
EXTERNAL:	L ST LOBBY WARD		1	1	LITCO BRYCE, J H	1	1		
	NOAC POORE, W.		1	1	NOAC QUEENER, DS	1	1		
	NRC PDR		1	1	NUDOCS FULL TXT	1	1		

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 25

A04

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T





Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-00995 - GRO/DGM/KR
July 7, 1997

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Docket No. STN 50-528
License No. NPF-41
Licensee Event Report 97-002-00**

Attached please find Licensee Event Report (LER) 97-002-00 prepared and submitted pursuant to 10 CFR 50.73. This LER reports a violation of Technical Specifications due to missing the performance of a surveillance requirement for core protection calculators.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Daniel G. Marks, Section Leader, Nuclear Regulatory Affairs, at (602) 393-6492.

Sincerely,

GRO/DGM/KR/kr

Attachment

cc: E. W. Merschoff (all with attachment)
K. E. Perkins
F. L. Brush
INPO Records Center
9707150356 970707
PDR ADDCK 05000528
S PDR

IEE221

150070





11