## CATEGORY (

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

Document Control Branch (Document Control Desk)

ACCESSION NBR:9803250374 DOC.DATE: 98/03/12 NOTARIZED: NO DOCKET # FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528 AUTH.NAME AUTHOR AFFILIATION

OVERBECK,G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: Forwards LER 98-002-00, which repts an automatic reactor trip on low SG level due to insufficient main feedwater flow.LER do not contain commitments.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR \_ ENCL \_ SIZE: +5
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:STANDARDIZED PLANT

05000528E


4	RECIPIENT	COPIES		RECIPIENT	COPIES		G
	ID CODE/NAME PD4-2 PD		ENCL 1	ID CODE/NAME CLIFFORD, J		ENCL 1	0
INTERNAL:	ACRS	1	1 '	AEOD/CPD/RAB	2	2	R
	AEOD/SPD/RRAB	ī	ī	FYDE GENTLER	ī	์ ว	77
	NRR/DE/ECGB	1	1	NRR/DE/EELB	ī	ī	Y
	NRR/DE/EMEB	1	1	NRR/DRCH/HHFB	ī	ī	
	NRR/DRCH/HICB	1	1.	NRR/DRCH/HOLB	1	ī	1
	NRR/DRCH/HQMB	1	1	NRR/DRPM/PECB	1	ī.	
	NRR/DSSA/SPLB	1	1	NRR/DSSA/SRXB	1	1	
	RES/DET/EIB	1	1	RGN4 FILE 01	1	1	
			_				D
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BRYCE, J H	1	1	_
	NOAC POORE, W.	1	1	NOAC QUEENER, DS	1	1	O.
	NRC PDR	1	1	NUDOCS FULL TXT	1	1	•
4						•	C

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 2

A04





Palo Verde Nuclear **Generating Station** 

Gregg R. Overbeck Vice President **Nuclear Production** 

TE'\_ 602/393-5148 FAX 602/393-6077 Mail Station 7602 P.O. Box 52034 Phoenix, AZ 85072-2034

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Station P1-37 Washington, D.C. 20555-0001

192-01014 -- GRO/DGM/KR March 12, 1998

Dear Sirs:

Subject:

Palo Verde Nuclear Generating Station (PVNGS)

Unit 1

Docket No. STN 50-528 License No. NPF-41

Licensee Event Report 98-002-00

Attached please find Licensee Event Report (LER) 98-002-00 prepared and submitted pursuant to 10 CFR 50.73. This LER reports an automatic reactor trip on low steam generator (SG) level due to insufficient main feedwater flow. In addition to the reactor trip, the unit received an engineered safety feature actuation system actuation of the auxiliary feedwater system 2 (AFAS-2) on low SG-2 water level. Both emergency diesel generators started and ran unloaded as designed. This LER does not contain any commitments.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Daniel G. Marks, Section Leader, Nuclear Regulatory Affairs, at (602) 393-6492.

(all with attachment)

Sincerely.

Greggh. Sunline

GRO/DGM/KR/mah

**Attachment** 

Tezz

E. W. Merschoff CC:

> K. E. Perkins J. H. Moorman

**INPO Records Center** 

9803250374 98031

