

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK fields: 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80

CON'T fields: 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) WHILE PERFORMING AN ISI PROGRAM TEST, THE SERVICE WATER SUPPLY CHECK VALVE TO AB DIESEL, ESW-143, FAILED TO SEAT. THE DIESEL WAS MADE INOPERABLE PER T.S. 3.8.2.1 TO EFFECT REPAIRS. THE "SPLIT CENTER" SPRING LOADED CHECK VALVE WAS REBUILT USING ALL NEW INTERNAL PARTS AND TESTED TO THE SAME CRITERIA THAT DETECTED THE FAILURE. TEST RESULTS WERE SATISFACTORY AND THE DIESEL WAS RETURNED TO SERVICE. THIS EVENT DID NOT AFFECT PUBLIC HEALTH AND SAFETY.

SYSTEM CODE (W, A), CAUSE CODE (E), CAUSE SUBCODE (F), COMPONENT CODE (V, A, L, V, E, X), COMP. SUBCODE (L), VALVE SUBCODE (A), EVENT YEAR (7, 9), SEQUENTIAL REPORT NO. (0, 0, 6), OCCURRENCE CODE (0, 3), REPORT TYPE (L), REVISION NO. (0), ACTION TAKEN (A), FUTURE ACTION (Z), EFFECT ON PLANT (Z), SHUTDOWN METHOD (Z), HOURS (0, 0, 0, 0), ATTACHMENT SUBMITTED (N), NPRD-4 FORM SUB. (Y), PRIME COMP. SUPPLIER (A), COMPONENT MANUFACTURER (C, 1, 8, 2)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) THE FAILURE WAS DUE TO NORMAL WEAR OF THE SPLIT CENTER DISC OF THE 6 INCH, 150 PSI, CARBON STEEL CHECK VALVE, CENTERLINE PART NO. D-10495-26. THE DISC WAS WORN AT THE HINGE. NEW DISC, SEAT, SPRINGS AND STEM WERE INSTALLED. NO PROBLEMS WERE DETECTED ON SIMILAR CHECK VALVES WHICH WERE ALSO TESTED.

FACILITY STATUS (E), % POWER (1, 0, 0), OTHER STATUS (N/A), METHOD OF DISCOVERY (B), DISCOVERY DESCRIPTION (INSERVICE INSPECTION)

ACTIVITY CONTENT (Z), AMOUNT OF ACTIVITY (N/A), LOCATION OF RELEASE (N/A)

PERSONNEL EXPOSURES NUMBER (0, 0, 0), TYPE (Z), DESCRIPTION (N/A)

PERSONNEL INJURIES NUMBER (0, 0, 0), DESCRIPTION (N/A)

LOSS OF OR DAMAGE TO FACILITY TYPE (Z), DESCRIPTION (N/A)

PUBLICITY ISSUED (N), DESCRIPTION (N/A)

NAME OF PREPARER: DAVID G. WIZNER

PHONE: (616) 465-5901

dupes of 7902220115