

SUPPLEMENT TO LER #79-008/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THIS ALLOWED FOR ALIGNMENT OF THE LIMIT SWITCH AND VERIFIED THAT
THE APPROPRIATE ALARM/TRIP SIGNAL FUNCTIONED PROPERLY.
NO FURTHER ACTION IS PLANNED AT THIS TIME

