

APR 11 1979

Docket No. 50-315  
Docket No. 50-316

American Electric Power Service  
Corporation  
Indiana and Michigan Power Company  
ATTN: Mr. John E. Dolan  
Vice Chairman  
Engineering and Construction  
2 Broadway  
New York, NY 10004

Gentlemen:

Enclosed is IE Bulletin No. 79-06, which requires action by you with regard to your pressurized water reactor facilities with an operating license.

Based on our current understanding of the Three Mile Island accident sequence, and discussion with the designer of your pressurized water reactor, we have reason to believe that pressurizer level indication in your facilities may not provide reliable information regarding level in the reactor coolant system under certain transient or accident condition. You should immediately instruct your operating personnel accordingly. In addition, you should consider this possibility in responding to the enclosed bulletin.

Should you have any questions regarding this Bulletin or the actions required by you, please contact this office.

Sincerely,

James G. Keppler  
Director

Enclosure: IE Bulletin  
No. 79-06

cc w/encl:  
Mr. D. V. Shaller,  
Plant Manager  
Central Files  
Director, NRR/DPM  
Director, NRR/DOR  
PDR

790503006

Q 40 2  
GD

OFFICE	Local PDR NSIG	RIII	RIII	RIII	RIII
SURNAME	TIC Ronald Gallen, Michigan Public Service Commission			Heishman/dec 4/11/79	Keppler
DATE					