



**KHNP**

**KOREA HYDRO & NUCLEAR POWER CO., LTD**

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

November 13, 2017  
Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

Attention: Mr. William Ward  
Division of New Reactor Licensing

Docket No. 52-046  
MKD/NW-17-0360L

**Subject: Revised Response to RAI 116-8054 for Question 14.03.08-8 (Rev.1)**

- References:**
- 1) NRC Request for Additional Information 116-8054, dated July 27, 2015
  - 2) KHNP Letter MKD/NW-15-0109L, Response to RAI 116-8054 for Question on a 30-Day Response Cycle, dated September 1, 2015
  - 3) KHNP Letter MKD/NW-15-0186L, Response to RAI 116-8054 for Question on a 45-Day Response Cycle, dated October 7, 2015
  - 4) KHNP Letter MKD/NW-15-0204L, Response to RAI 116-8054 for Questions on a 60-Day Response Cycle, dated October 30, 2015

KHNP is hereby submitting the response to RAI 116-8054, dated July 27, 2015. The revised response addresses Question 14.03.08-8 changes Tag No. of containment building sump level and containment ICI cavity sump level. The enclosure provides the revised response to RAI 116-8054 for Question 14.03.08-8 (Rev.1) (Non-Proprietary).

If additional information or clarification is required, please contact Daegun Ahn, Director of KHNP Washington DC Center at [ahn.daegun@khnp.co.kr](mailto:ahn.daegun@khnp.co.kr) or 703-388-0592.

Sincerely,

Han-gon Kim  
Project Manager  
Advanced Reactors Development Laboratory  
Korea Hydro & Nuclear Power Co., Ltd.

Enclosure: Revised Response to RAI 116-8054 for Question 14.03.08-8 (Rev.1) (Non-Proprietary)

## **Enclosure**

Revised Response to RAI 116-8054 for Question 14.03.08-8 (Rev.1)

(Non-Proprietary)

November 13, 2017