

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Fluke Electronics Corporation 6045 Cochran Road Solon, OH 44139</p> <p>REPORT NUMBER(S) 2017001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>	
<p>3. DOCKET NUMBER(S)</p> <p>030-30726</p>	<p>4. LICENSE NUMBER(S)</p> <p>34-25957-03E</p>	<p>5. DATE(S) OF INSPECTION</p> <p>October 17 - November 8, 2017</p>

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Kevin G. Null		11/5/17
BRANCH CHIEF	David T. McCraw		11/13/17

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Fluke Electronics Corporation 6045 Cochran Road Solon, OH 44139 REPORT NUMBER(S) 2017001		2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-30726	4. LICENSE NUMBER(S) 34-25957-03E	5. DATE(S) OF INSPECTION October 17 - November 8, 2017	

6. INSPECTION PROCEDURES USED 87128	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03251	2. PRIORITY 5	3. LICENSEE CONTACT Mark Svajger, RSO	4. TELEPHONE NUMBER (440) 542-8059
---------------------------------	----------------------	--	---

- Main Office Inspection Next Inspection Date: 10/17/2022
- Field Office Inspection _____
- Temporary Job Site Inspection _____

PROGRAM SCOPE

This was a routine, unannounced inspection of Fluke Electronics Corporation's license that authorized distribution of sealed sources of chlorine-36, nickel-63, and radionuclides described in 10 CFR Part 30, Section 30.71, schedule B as exempt quantities incorporated into radiation measuring instruments, electrons tubes, and as standards or check sources, respectively. The exempt distribution license does not authorize the possession of byproduct material. The licensee also holds a state of Ohio license, which authorized the possession of byproduct material.

PERFORMANCE OBSERVATIONS

The inspector interviewed the radiation safety officer (RSO) at the main office, located in Solon, Ohio. The RSO provided an overview of the licensed program. The inspector reviewed and observed examples of products that contained sealed sources, shipping records of licensed material contained in devices, product labeling, and package insert information. The inspector also reviewed the licensee's annual material transfer reports for calendar years 2013 - 2016.

No violations of NRC requirements were identified during this inspection.