



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

December 28, 1979

Operating License DPR-58
Docket # 50-315

Mr. J. G. Keppler, Regional Director
Office Of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This report is submitted as required by Technical Specification 3.3.3.4, as the required Meteorological Monitoring Instrumentation was inoperable from December 12, 1979 until December 24, 1979.

The Meteorological Monitoring Instrumentation was taken out-of-service on December 12, for the installation of new meteorological equipment, of a modified design, to improve Meteorological System operability during the winter months. The completion of the new equipment installation was delayed by several days of adverse weather conditions, preventing any work on the weather tower.

After completing the installation and calibration of the new equipment, the Meteorological Monitoring Instrumentation was determined to be operable on December 24, 1979. No gaseous releases were made during this time period.

Very truly yours,

D. V. Shaller
Plant Manager

/ms

cc: J. E. Dolan
R. S. Hunter
R. W. Jurgensen
R. F. Kroeger
R. Kilburn
R. E. Masse RO:III
R. C. Callen MPSC
C. Charnoff, Esq.

G. Olson
J. M. Hennigan
PNSRC
J. F. Stietzel
E. L. Townley
Dir., IE (20 copies)
Dir., MIPC (2 copies)
Dir. of Licensing

dup of
8001070344
8001250486

