

Appendix A

NOTICE OF VIOLATION

American Electric Power Service
Corporation

Docekt No. 50-315; 50-316

Based on the inspection conducted from December 1, 1979 - January 11, 1980, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. This item is an infraction and applies to both units.

PMI 2260 "Standing Orders and Special Instructions" requires personnel to initial and date Standing Orders, or requires that supervisors initial that subordinates have had the Order communicated to them.

Contrary to this requirement, on January 9, 1980, the inspector observed that the latest OSO's (including those implementing NUREG-0578 recommendations) had not been reviewed by Unit 1 or Unit 2 licensed operators. Technical Specification 6.8.1 requires implementation of procedures.

8004040 440