

AUG 04 1983

Docket No. 50-316

American Electric Power Service Corporation
ATTN: Mr. John E. Dolan, Vice Chairman
Engineering & Construction
1 Riverside Plaza
Columbus, Ohio 43216

Gentlemen:

The staff of the Division of Licensing (DL) has provided copies of the following letters filed by your company that provide data required by two license conditions of License No. DPR-74 for Unit No. 2 of the Donald C. Cook Nuclear Plant. It is our understanding that the DL staff will have to review these submittals to determine whether the license conditions have been satisfactorily fulfilled before they can consider deletion of these conditions from License No. DPR-74.

1. June 1 and 2, 1978 Letters (AEP:NRC:00021 and 00023) regarding qualification of Barton Transmitters, and
2. September 22, 1978 Letter (AEP:NRC:00090) regarding postulated Steam Line Break Inside Containment.

Based on information provided by the DL staff as a result of a preliminary fee review of your letters, it has been determined that each review will involve the consideration of a single safety issue. Therefore, a Class III fee of \$4,000 is required for each of the above items. It is requested that your company remit the sum of \$8,000 to this office for items 1 and 2 above. If the DL staff's final reviews of these submittals reveal that these fees are not correct, you will be notified and any necessary adjustments will be made.

DISTRIBUTION:

PDR
LPDR
D. Wigginton, ORB-1
C. Parrish, ORB-1
Regulatory Docket 50-316 ✓
LFMB Reactor File
LFMB Pending Check File
R. Diggs, LFMB
LFMB R/F

Sincerely,

Original Signed by
Wm. O. Miller

William O. Miller, Chief
License Fee Management Branch
Office of Administration

WOM

8308110374 830804
PDR ADDCK 05000316
PDR

LFMB:ADM <i>RMD</i>	LFMB:ADM <i>CJH</i>	LFMB:ADM <i>WOM</i>				
RMDiggs:rmf	CJHalloway	WOMiller				
8/3/83	8/3/83	8/3/83				



[The text in this block is extremely faint and illegible, appearing as scattered black specks and noise across the page.]