

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8503270238 DOC. DATE: 85/03/20 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH. NAME AUTHOR AFFILIATION
 ALEXICH, M.P. Indiana & Michigan Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director


SUBJECT: Informs of coding error found in program used for LOCA-ECCS analysis submitted in XN-NF-83-61, "DC Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure." Exxon-reperformed analysis w/coding error corrected.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL φ SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES: 05000315
 OL: 10/25/74

	RECIPIENT ID CODE/NAME		COPIES LTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTR ENCL
	NRR ORB1 BC	01	7				
INTERNAL:	ACRS	09	6		ADM/LFMB		1
	ELD/HDS3		1		NRR/DE/MTEB		1
	NRR/DL DIR		1		NRR/DL/ORAB		1
	NRR/DL/TSRG		1		NRR/DSI/METB		1
	NRR/DSI/RAB		1		REG FILE	04	1
	RGN3		1				
EXTERNAL:	LPDR	03	1		NRC PDR	02	1
	NSIC	05	1				

TOTAL NUMBER OF COPIES REQUIRED: LTR 26 ENCL 25



INDIANA & MICHIGAN ELECTRIC COMPANY

P.O. BOX 16631
COLUMBUS, OHIO 43216

March 20, 1985
AEP:NRC:0745T

Donald C. Cook Nuclear Plant Unit No. 1
Docket No. 50-315
License No. DPR-58
REVISION TO ANALYSIS WHICH SUPPORTED A TECHNICAL SPECIFICATION CHANGE

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Denton:

Exxon Nuclear Company informed AEP of a coding error in their LOCA-ECCS analysis. This coding error was found in a program used for the LOCA-ECCS analysis of the D. C. Cook Nuclear Plant Unit 1. The analysis in question was submitted to NRC in XN-NF-83-61, "D. C. Cook Unit 1 LOCA-ECCS Analysis for Extended Exposure," for an exposure of 48,000 MWD/MTU. The error was in the TOODEE2 code which is used for the reflood/heatup calculation. The error resulted in an increase in the heat transfer coefficient during reflood, thus underpredicting the peak cladding temperature (PCT).

Exxon has informed us that the analysis has been reperformed for this high burnup case with the coding error corrected. They indicated that the revised PCT is 1785°F, which is an increase of 49°F. This revised PCT still satisfies the requirements of 10CFR50.46. Therefore, we believe that there is no further action required on this matter.

Exxon Nuclear Company has advised us that they will inform you of the coding error formally as required by 10 CFR 21.21. They have further advised us that this coding error does not affect the analyses performed for D. C. Cook Nuclear Plant Unit 2.

This document has been prepared following Corporate procedures which incorporate a reasonable set of controls to insure its accuracy and completeness prior to signature by the undersigned.

Very truly yours,



M. P. Alexich
Vice President

4/20/85
3-20-85

JLB:wj

8503270238 850320
PDR ADDCK 05000315
PDR

Acc
1/0

THE UNIVERSITY OF CHICAGO
DEPARTMENT OF CHEMISTRY
5800 S. UNIVERSITY AVENUE
CHICAGO, ILLINOIS 60637

RECEIVED
MAY 15 1964

TO THE DIRECTOR
OF THE UNIVERSITY OF CHICAGO
FROM THE DEPARTMENT OF CHEMISTRY
RE: [Illegible]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

[Illegible text]

Mr. Harold R. Denton, Director

- 2 -

March 20, 1985

cc: John E. Dolan
W. G. Smith, Jr. - Bridgman
George Bruchmann
R. C. Callen
R. Charnoff
NRC Resident Inspector - Bridgman
G. F. Owsley, ENC - Richland, WA

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that this is essential for ensuring the integrity of the financial statements and for providing a clear audit trail.

2. The second part of the document outlines the specific procedures that should be followed when recording transactions. It details the steps from identifying the transaction to posting it to the appropriate ledger account.

3. The third part of the document discusses the importance of reconciling the accounts. It explains how regular reconciliations help to identify and correct errors before they become more significant.

4. The fourth part of the document discusses the importance of maintaining proper documentation. It highlights the need to keep all supporting documents, such as invoices and receipts, organized and accessible.

5. The fifth part of the document discusses the importance of reviewing the records regularly. It explains how this helps to ensure that the records are up-to-date and accurate.