

JUN 21 1985

Docket No. 50-315
Docket No. 50-316/85-07

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216


Gentlemen:

Thank you for your letter dated June 14, 1985, informing us of the steps you have taken to correct the violations which we brought to your attention in our letter dated April 29, 1985. With one exception, we find your response to be acceptable.

Mr. H. A. Walker of my staff and Mr. P. Barrett of your organization discussed the matter on June 18, 1985. In that regard, we understand that your organization will provide during future inspections documented evidence of increased management attention relative to both procedural adherence and the resolution of quality problems.

Please contact Mr. Frank Hawkins of my staff (312-790-5555) with any questions you may have regarding this matter.

Sincerely,



R. L. Spessard, Director
Division of Reactor Safety

cc w/ltr dtd: 6/14/85:
W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

8506270507 850621
PDR ADOCK 05000315
Q PDR

RIII
Walker/lc
6/21/85

RIII
Hawkins
6/21
RIII
Wright
a/a

RIII
Reyes
6/21

RIII
Spessard
6/21

111
1201

1948

1948

1948

1948

1948

1948

1948

1948

1948

1948

1948

1948

1948