

DWB

FEB 11 1986

Docket No. 50-315/85-41
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen, J. K. Heller, C. L. Wolfson, E. R. Swanson, and C. D. Anderson of this office on December 10, 1985 through January 20, 1986, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff during the course of and at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

8602250114 860211
PDR ADOCK 05000315
Q PDR

11
JEO1

1950



American Electric Power Service
Corporation

2

FEB 11 1986

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by N.J. Chrissotimos"

N. J. Chrissotimos, Chief
Reactor Projects Branch 2

Enclosures:

1. Notice of Violation
2. Inspection Reports
No. 50-315/85041(DRP);
No. 50-316/85041(DRP)

cc w/enclosures:

W. G. Smith, Jr., Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

RIII

Jis
Suermann/jp

2/6/86
2/16/86

RIII

[Signature]
Hehl

RIII

Chrissotimos

FEB 11 1987

