

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-315/86012(DRSS); 50-316/86012(DRSS)

Docket Nos. 50-315; 50-316 Licenses No. DPR-58; DPR-74 Safeguards Group IV

Licensee: American Electric Power Service Corporation
Indiana and Michigan Electric Company
1 Riverside Plaza
Columbus, OH 43216

Facility Name: Donald C. Cook Nuclear Power Plant, Units 1 and 2

Meeting At: Region III Office, and Donald C. Cook Site, Budgman, MI

Meeting Conducted: February 20 and March 7, 1986

Type of Meeting: Announced Security Management Meeting

Inspector: *J. R. Creed*
J. R. Creed, Chief
Safeguards Section

3/11/86
Date

Approved By: *W. L. Axelson*
W. L. Axelson, Chief
Nuclear Materials Safety
and Safeguards Branch

3/12/86
Date

Inspection Summary

Inspection on February 20 and March 7, 1986 (Reports No. 50-315/86012(DRSS);
No. 50-316/86012(DRSS))

Areas Inspected: This was a management meeting held to discuss the licensee's development of a Performance Improvement Program. The meeting involved approximately three hours by one inspector.

Results: No violations were identified. Information regarding the licensee's progress, development, and content of a performance improvement program was exchanged. The licensee agreed to continue the development of their program.

8603170154 860312
PDR ADOCK 05000315
Q PDR

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled



1944

1944

1944