

MAR 11 1986

Docket No. 50-315/86-06
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by M. L. McCormick-Barger of this office on February 3, 1986 through February 26, 1986, of activities at D. C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. A. A. Blind and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identified areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

8603170364 860311
PDR ADDCK 05000315
Q PDR

Enclosure: Inspection Reports
No. 50-315/86006(DRS);
No. 50-316/86006(DRS)

See Attached Distribution

RIII
CML/son
McCormick-Barger/bls
Yes

RIII
chrcn
Ring

RIII
CML
Hehl

RIII
JA
Harrison
3/11

1/1

IEO1



American Electric Power Service
Corporation

2

MAR 11 1986

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager
DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Nuclear Facilities and

Environmental Monitoring

Section