## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8704280160 DOC. DATE: 87/04/16 NOTARIZED: NO DOCKET # FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316 AUTH. NAME AUTHOR AFFILIATION

DEMOND, W. G. ECIP. NAME

Region 3, Office of Director

RECIPIENT AFFILIATION

DOLAN, J. E.

American Electric Pouer Service Corp.

DOLAN, J. E.

Indiana & Michigan Electric Co.

SUBJECT: Forwards Safety Insp Repts 50-315/87-07 & 50-316/87-07 on

870224-0331. No violations noted.

DISTRIBUTION CODE: 1E01D COPIES RECEIVED: LTR / ENCL / SIZE: 2+25 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

## NOTES:

	RECIPIENT	COPIES LTTR ENCL		RECIPIENT	COPIES LTTR ENCL	
	ID CODE/NAME PD3-3 LA	1	O	ID CODE/NAME PD3-3 PD	1	1
	WIGGINGTON, D	1	1			
INTERNAL:	AEOD	1	1	DEDRO	1	1
	ENF LIEBERMAN	1	1	MRR ROE, M. L	1	1
	NRR/ADT	1	1	MRR/DOEA DIR	1	1
	NRR/DREP/EPB	j	1	MRR/DREP/RPB	2	2
	MRR/DRIS DIR	1	1	NRR/PMAS/ILRR	1	1
-	DGC\HDS1	1	1	REG ELLB	1	1.
	KES SPEIS, T	1	1	RGN3 FILE 01	. 1	i
E NAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			



Docket No. 50-315 Docket No. 50-316 APR 16 1987

American Electric Power Service Corporation Indiana and Michigan Electric Company ATTN: Mr. John E. Dolan Vice Chairman Engineering and Construction 1 Riverside Plaza Columbus, OH 43216

## Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen and J. K. Heller of this office on February 24 through March 31, 1987 of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with A. A. Blind, and others of your staff during the course of and at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

ORIGINAL SIGNED BY W. G. GULDEMOND

W. G. Guldemond, Chief Projects Branch 2

Enclosure:


Inspection Reports


No. 50-315/87007(DRP); and No. 50-316/87007(DRP)

See Attached Distribution

RIII &

Creed (Para. 10)





cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

