

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8708100427 DOC. DATE: 87/07/30 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 GULDEMOND, W. G. Region 3, Office of Director
 RECIP. NAME RECIPIENT AFFILIATION
 DOLAN, J. E. American Electric Power Service Corp.
 DOLAN, J. E. Indiana & Michigan Electric Co.

SUBJECT: Forwards Insp Repts 50-315/87-14 & 50-316/87-14 on
 870616-0713. No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+15
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD3-3 PD		1	1		WIGGINGTON, D		2	2
INTERNAL:	AEOD		1	1		DEDRO		1	1
	NRR MORISSEAU, D		1	1		NRR/DOEA DIR		1	1
	NRR/DREP/EPB		1	1		NRR/DREP/RPB		2	2
	NRR/DRIS DIR		1	1		NRR/PMAS/ILRB		1	1
	DE LIEBERMAN, J		1	1		OGC/HDS1		1	1
	<u>REG FILE</u>		1	1		RES DEPY GI		1	1
	RGN3 FILE 01		1	1					
INTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					

JUL 30 1987

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen and J. K. Heller of this office on June 16 through July 13, 1987, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff during the course of and at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

ORIGINAL SIGNED BY I. N. JACKIW

W. G. Guldemon, Chief
Projects Branch 2

Enclosure: Inspection Reports
No. 50-315/87014(DRP); and
No. 50-316/87014(DRP)

See Attached Distribution

RIII
[Signature]
for Kazmar/lms
7/30/87

RIII
[Signature]
for Burgess
7/30/87

RIII
[Signature]
for Guldemon
7/30

8708100427 870730
PDR ADDCK 05000315
G PDR

11
IEOI



American Electric Power Service
Corporation

2

JUL 30 1987

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager
DCS/RSB (RIDS)

Licensing Fee Management Branch
Resident Inspector, RIII

D. Wigginton, Licensing Project
Manager, NRR

Ronald Callen, Michigan
Public Service Commission

EIS Coordinator, USEPA
Region 5 Office

Nuclear Facilities and
Environmental Monitoring
Section

