

## ADMINISTRATIVE CONTROLS

---

### 6.3 FACILITY STAFF QUALIFICATIONS

6.3.1 Each member of the facility staff shall meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable position, except for (1) the Radiation Protection Supervisor who shall meet or exceed the qualifications of Regulatory Guide 1.8, September 1975, and (2) the Shift Technical Advisor who shall have a bachelor's degree or equivalent in a scientific or engineering discipline with specific training in plant design, and response and analysis of the plant for transients and accidents.

### 6.4 TRAINING


6.4.1 A retraining and replacement training program for the facility staff shall be maintained under the direction of the Training Coordinator and shall meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971 and Appendix "A" of 10 CFR Part 55.

### 6.5 REVIEW AND AUDIT

#### 6.5.1 PLANT NUCLEAR SAFETY REVIEW COMMITTEE (PNSRC)

##### FUNCTION

6.5.1.1 The PNSRC shall function to advise the Plant Manager on all matters related to nuclear safety.



## 6.0 ADMINISTRATIVE CONTROLS

---

### 6.3 FACILITY STAFF QUALIFICATIONS

6.3.1 Each member of the facility staff shall meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable positions, except for (1) the Radiation Protection Supervisor who shall meet or exceed the qualifications of Regulatory Guide 1.8, September 1975, and (2) the Shift Technical Advisor who shall have a bachelor's degree or equivalent in a scientific or engineering discipline with specific training in plant design, and response and analysis of the plant for transient and accidents.

### 6.4 TRAINING

6.4.1 A retraining and replacement training program for the facility staff shall be maintained under the direction of the Training Coordinator and shall meet or exceed the requirements and recommendations of Section 5.5 of ANSI N18.1-1971 and Appendix "A" of 10 CFR Part 55.

### 6.5 REVIEW AND AUDIT

#### 6.5.1 PLANT NUCLEAR SAFETY REVIEW COMMITTEE (PNSRC)

6.5.1.1 The PNSRC shall function to advise the Plant Manager on all matters related to nuclear safety.

#### COMPOSITION

6.5.1.2 The PNSRC shall be composed of the:

Chairman:	Plant Manager or Designee
Member:	Assistant Plant Manager - Maintenance
Member:	Assistant Plant Manager - Operations
Member:	Operations Superintendent
Member:	Technical Superintendent - Engineering
Member:	Technical Superintendent - Physical Sciences
Member:	Maintenance Superintendent
Member:	Plant Radiation Protection Supervisor
Member:	QC Superintendent