

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8803180247 DOC. DATE: 88/03/11 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME AUTHOR AFFILIATION
 SHAFER, W.D. Region 3, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Insp Repts 50-315/88-10 & 50-316/88-11 on 880210-18. No violations noted.

DISTRIBUTION CODE: IE06D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+14
 TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL
	PD3-3 LA	1		0	PD3-3 PD	1		1
	STANG, J	1		1				
INTERNAL:	AEOD/DOA	1		1	AEOD/DSP	1		1
	NMSS/LLOB 5E4	1		1	NMSS/SJOB 4E4	1		1
	NRR/DLPQ/PEB11B	1		1	NRR/DOEA/EAB11E	1		1
	NRR/DREP/EPB10D	1		1	NRR/DREP/RPB10A	2		2
	NRR/PMAS/ILRB12	1		1	OGC 15-B-18	1		1
	REG FILE 02	1		1	RES	1		1
	RES/DRPS DIR	1		1	RGN3 FILE 01	1		1
	RGN2/DRSS/EPRPB	1		1	RGN4 MURRAY, B	1		1
INTERNAL:	LPDR	1		1	NRC PDR	1		1
	NSIC	1		1				

TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 22

R
I
D
S
/
A
D
D
S

MAR 11 1988

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Dr. R. B. Holtzman and Mr. M. C. Schumacher of this office on February 10-18, 1988, of activities at D. C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DRP-58 and No. DRP-74, and to the discussion of our findings with Mr. W. Smith, Jr. and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W.D. Shafer"

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Reports
No. 50-315/88010(DRSS);
No. 50-316/88011(DRSS)

See Attached Distribution

8803180247 880311
PDR ADDCK 05000315
0 ncn

IE06
1/1

Indiana Michigan Power Company

2 MAR 11 1988

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)

Licensing Fee Management Branch
Resident Inspector, RIII

Ronald Callen, Michigan
Public Service Commission

EIS Coordinator, USEPA
Region 5 Office

Michigan Department of
Public Health

RIII
[Signature]
Holtzman/crr g/b

RIII
[Signature]
Schumacher
[Signature]

(yes)
RIII
[Signature]
Burgess
3/11

RIII
[Signature]
Spaen