

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Halliburton Energy Services, Inc. 35840 and 37170 Sterling Hwy Sterling, Alaska		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511	
REPORT NO.: 2017-002			
3. DOCKET NUMBER 030-06392	4. LICENSE NUMBER 42-01068-07	5. DATE(S) OF INSPECTION 8/28 through 9/6, 2017	

**LICENSEE:**  
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	James L. Thompson		9/13/2017
BRANCH CHIEF	Michael C. Hag		10/30/2017

Non-Public   
  Sensitive – Security-Related   
  Public   
  Non-Sensitive

## Thompson, James

---

**From:** Thompson, James  
**Sent:** Wednesday, September 13, 2017 11:41 AM  
**To:** 'Jeremy Daniel'  
**Cc:** Renee Huntman; Joseph Baninge-Daanaah  
**Subject:** RE: Contact Information  
**Attachments:** SR4-KM554-C17091310230.pdf

**Importance:** High

All:

Please find enclosed the inspection report for the inspection performed by the NRC on 8/28/2017 at your field offices in Sterling, Alaska; the final exit meeting for this inspection was held with Jeremy Daniel on 9/6/2017. Please let me know if you have any questions regarding this inspection.

Thank you,

James L. Thompson  
Senior Health Physicist  
U.S. NRC, Region IV  
Arlington, Texas

---

**From:** Jeremy Daniel [mailto:Jeremy.Daniel@Halliburton.com]  
**Sent:** Wednesday, September 06, 2017 2:47 PM  
**To:** Thompson, James <James.Thompson@nrc.gov>  
**Cc:** Renee Huntman <Renee.Huntman@Halliburton.com>; Joseph Baninge-Daanaah <josephB.Baninge-Daanaah@Halliburton.com>  
**Subject:** [External\_Sender] Contact Information

James,

Please see below for my contact information. You mentioned you may send the report next week. If that's the case could I trouble you to include the attached contacts in the CC line of the email? I may be out of office but would like for them to receive it as well. Thank you very much for the help.

---

### Jeremy Daniel

WP Sr. Service Manager-Alaska

6900 Arctic Blvd  
Anchorage, AK 99518-2146  
Email: [jeremy.daniel@halliburton.com](mailto:jeremy.daniel@halliburton.com)  
Office: +1 907-275-2625  
Mobile: +1 907-230-2291

Follow Halliburton: [LinkedIn](#) | [Facebook](#) | [Twitter](#) | [YouTube](#) | [Blog](#)