

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 8812190336 DOC. DATE: 88/12/14 NOTARIZED: NO DOCKET #  
SICIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
AUTH. NAME: WRIGHT, G.C. AUTHOR AFFILIATION: Region 3, Ofc of the Director  
RECIP. NAME: ALEXICH, M.P. RECIPIENT AFFILIATION: Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Insp Repts 50-315/88-25 & 50-316/88-29 on  
881031-1104. No violations noted.

DISTRIBUTION CODE: IE42D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+17  
TITLE: Operator Licensing Examination Reports

### NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME	LTR	ENCL	
	PD3-1 PD		1	1	STANG, J	1	1	
INTERNAL:	AEOD/DSP/TPAB		1	1	NRR MORISSEAU, D	1	1	
	NRR/DLPQ/HFB 10		1	1	NRR/DLPO/OLB 10	2	2	
	NUDOCS-ABSTRACT		1	1	<del>REG FILE 02</del>	1	1	
	RGN3 FILE 01		1	1				
EXTERNAL:	LPDR		1	1	NRC PDR	1	1	
	NSIC		1	1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 13 ENCL 13

I  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S



DEC 14 1988

Docket No. 50-315  
Docket No. 50-316

Indiana Michigan Power Company  
ATTN: Mr. Milton P. Alexich  
Vice President  
Nuclear Operations Division  
1 Riverside Plaza  
Columbus, OH 43216

Gentlemen:

This refers to the unannounced inspection conducted by Messrs. D. J. Damon and J. A. Hopkins of this office on October 31 through November 4, 1988, of the Operator Requalification Program at D. C. Cook Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. G. Smith and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. Our inspection team concluded that you are fully meeting your commitments to improve the Requalification Training Program and have made significant progress towards fully implementing the new requalification examination process.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed By T. M. Burdick

Geoffrey C. Wright, Chief  
Operations Branch

8812190336 881214  
PDR ADOCK 05000315  
R PDC

Enclosure: Inspection Reports  
No. 50-315/88025(DRS);  
No. 50-316/88029(DRS)

See Attached Distribution

Yes  
RIII  
Hopkins/sv  
JH

RIII  
Damon  
D

RIII  
Burdick  
12/14/88

RIII  
Burgess  
12/14/88

B/jr  
RIII  
Wright  
12/14/88

TE-42  
111

DEC 14 1988

Indiana Michigan Power Company

2

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

