

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8812200108 DOC. DATE: 88/12/09 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME: AUTHOR AFFILIATION
 HARRISON, J.J. Region 3, Ofc of the Director
 RECIP. NAME: RECIPIENT AFFILIATION
 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Safety Insp Rept 50-316/88-26 on 880907-1129 & safety evaluation. No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+19
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL
	PD3-1 PD	1		1	STANG, J	1		1
INTERNAL:	AEOD	1		1	DEDRO	1		1
	NRR SHANKMAN, S	1		1	NRR/DLPQ/PEB 11	1		1
	NRR/DLPQ/QAB 10	1		1	NRR/DOEA DIR 11	1		1
	NRR/DREP/EPB 10	1		1	NRR/DREP/RPB 10	2		2
	NRR/DRIS DIR 9A	1		1	NRR/PMAS/ILRB12	1		1
	NUDOCS-ABSTRACT	1		1	OE HEBERMAN, J	1		1
	OGC/HDS1	1		1	<u>REG FILE</u> 02	1		1
	RGN3 FILE 01	1		1				
EXTERNAL:	LPDR	1		1	NRC PDR	1		1
	NSIC	1		1	RESL MARTIN, D	1		1


NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 22

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



DEC 9 1988

Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the special safety inspection conducted by Mr. J. Jacobson and others of this office and NRC Headquarters on September 7 through November 29, 1988, of activities at the D. C. Cook Nuclear Plant, Unit 2, authorized by NRC Operating License No. DPR-74 and to the discussion of our findings with Mr. J. White at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8812200108 881209
PDR ADDCK 05000316
Q PNU

Original signed by J. J. Harrison

J. J. Harrison, Chief
Engineering Branch

Enclosures:

1. Inspection Report
No. 50-316/88026(DRS)
2. NRR memo dtd 11/9/88
3. SER, "Evaluation of the Cracking
of the Steam Generator Nozzle
to Reactor Coolant Piping Welds"

See Attached Distribution

Yes
RIII
[Signature]
Jacobson/jk
12/08/88

RIII
[Signature]
Westberg
12/8/88

Yes
RIII
[Signature]
Liu
12/8/88

Yes
RIII
[Signature]
Burgess
12/8/88

RIII
[Signature]
Danielson
12/8/88

RIII
[Signature]
Harrison
12/8/88

[Handwritten initials]



Indiana Michigan Power Company

2

DEC 9 1988

Distribution

cc w/enclosures:
W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health