

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 8903010126 DOC. DATE: 89/02/15 NOTARIZED: NO DOCKET #
 ACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME AUTHOR AFFILIATION
 GREGER, L.R. Region 3, Ofc of the Director.
 RECIP. NAME RECIPIENT AFFILIATION
 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Insp Repts 50-315/89-06 & 50-316/89-06 on I
 890130-0202. No violations noted.

DISTRIBUTION CODE: IE35D COPIES RECEIVED: LTR (ENCL (SIZE: 2+S D.
 TITLE: Emergency Preparedness-Appraisal/Confirmatory Action Ltr/Exercise Rep S

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES		
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL	
	PD3-1 PD		1	1	STANG, J		1	1	/
INTERNAL:	ARM/DAF/LFMB		1	0	NRR/DREP/EPB 10		1	1	D
	NRR/PMAS/ILRB12		1	1	NUDOCS-ABSTRACT		1	1	D
	REG FILE 02		1	1	RGN3 FILE 01		1	1	S
	RGN2/DRSS/EPRPB		1	1					
EXTERNAL:	LPDR		1	1	NRC PDR		1	1	
	NSIC		1	1					

R
I
D
S
/
A
D
D
S

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 12 ENCL 11



FEB 15 1989

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President.
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Ms. M. J. Smith of this office on January 30-February 2, 1989 of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operation Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with you, Mr. W. G. Smith, and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


L. Robert Greger, Chief
Reactor Projects Branch

8903010126 890215
PDR ADOCK 05000315
Q FFC

Enclosure: Inspection Reports
No. 50-315/89006(DRSS);
No. 50-316/89006(DRSS)

See Attached Distribution

RIII
wgs
Smith/ib

yes

RIII
wgs
Snell

yes
2/15/89

RIII
Burgess

2/15/89

RIII
Greger

2/15

IE35
11

Indiana Michigan Power
Company

2 FEB 15 1989

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)

Licensing Fee Management Branch
Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region-5 Office

Michigan Department of
Public Health

D. Bement, FEMA, RV

W. Travers, EPB, NRR