

CHARLES CENTER • P.O. BOX 1475 • BALTIMORE, MARYLAND 21203

February 25, 1986

U. S. Nuclear Regulatory Commission Region I		Docket Nos.	50-317 50-318
631 Park Avenue King of Prussia, PA 19406		License Nos.	DPR-53 DPR-69
ATTENTION:	Mr. Thomas T. Martin, Director Division of Radiation Safety & Safeguards		

SUBJECT: Inspection Report 50-317(85-31,)50-318/85-26; BG&E Response to REFERENCE: (a) BG&E letter from Mr. J. A. Tiernan to Mr. Thomas T. Martin, dated January 13, 1986

Reference (a) responded to finding 317/85-31-01 from the subject NRC Inspection Report by stating, in part, that the results of an evaluation of Control Room envelope inleakage and, if necessary, a Control Room Operator dose calculation would be provided by February 1, 1986. Due to an overly optimistic estimate of the effort required, the results of the subject evaluation have been delayed and will be provided by March 7, 1986.

We regret any inconvenience caused by this delay. Should you have further questions regarding this matter, we will be pleased to discuss them with you.

Very truly yours,

M. E. Bowman General Supervisor Technical Services Engineering

MEB/MTF/dlm

cc: D. A. Brune, Esquire J. E. Silberg, Esquire D. H. Jaffe, NRC T. Foley, NRC





n de la constante de

1 - D m. 1 (,

ан сторон сто Сторон сторон

م م د از از می کشور از می می م

÷

ъ. ₁. с. ч

ø

1888 NVB ... 3 BILIS: 31 VECEIAED-BEGION

۰.

......