i} <b>≁</b> ■	CALEGORI 1	
	REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)	
	NBR:9909220125 DOC.DATE: 99/08/23 NOTARIZED: NO -315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M	DOCKET #
	316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M	
BAKKEN, A RECIP.N	.C. Indiana Michigan Power Co.	
4	Records Management Branch (Document Control Desk)	
SUBJECT:	Forwards revised page 2 to "1998 Annual Environ Operating Rept," for DC Cook Nuclear Plant,correcting omission to App I.	
		4

᠈᠉ᡎᡓᡊᡣᡡ᠈

7

DISTRIBUTION CODE: IE25D COPIES RECEIVED:LTR  $\frac{1}{2}$  ENCL OTITLE: Environmental Monitoring Rept (per Tech Specs)

NOTES:

RECIPIENT	COPIES	RECIPIENT	COPIES	G,
ID CODE/NAME	LTTR ENCL	ID CODE/NAME	LTTR ENCL	0
BARNHILL, E	1 1	STANG, J	1 1	_
INTERNAL: FILE CENTER 01 7		NRR/DIPM/EPHP		R
RGN3 FILE		NRR/DIPM/EPHP	- 1	v
	- T			*
EXTERNAL: NRC PDR	1 1		•	
•	1			1

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

Er-

C

Α

Т

E

D

0

C

U

Μ

Έ

N

т

3

SIZE:

+1

Indiana Michigan Power Company CookNuclear Plant One Cook Plant Bridgman, M49106 616 465 5901

1



C0899-05

August 23, 1999

Docket Nos.: 50-315 50-316

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Stop O-P1-17 Washington, D.C. 20555-0001

## Donald C. Cook Nuclear Plant Units 1 and 2 CORRECTION TO 1998 ANNUAL ENVIRONMENTAL OPERATING REPORT

Reference: Letter from A. C. Bakken III to NRC dated April 30, 1999, "Donald C. Cook Nuclear Plant Units 1 and 2, ANNUAL ENVIRONMENTAL OPERATING REPORT, JANUARY 1, 1998, TO DECEMBER 31, 1998", (AEP:NRC:0806S)

The purpose of this letter is to correct an omission to Appendix I, Non-Routine Reports section of the 1998 Annual Environmental Operating Report, which was transmitted with the referenced letter.

During a routine audit of the Environmental Protection Plan, it was identified that a spill from the heating boiler on August 1, 1998 had not been reported in the 1998 Annual Environmental Operating Report. A revised page is enclosed with the correction marked in the margin. Please replace page 2 of Appendix I with the corrected page.

This condition has been entered into the corrective action program.

Should you have any questions, please contact Mr. Gordon Arent, Assistant Director of Regulatory Affairs, at (616) 465-5901, extension 1575.

Sincerely,

A. C. Bakken III Site Vice President

770823

PDR

ADOCK 05000315

/dms

9909220125

PDR

Enclosure

G

220021

U, S. Nuclear Regulatory Commission
Page 2

\*

¢

C0899-05

c: J. E. Dyer MDEQ - DW & RPD NRC Resident Inspector, w/enclosure R. P. Powers R. Whale MPSC 1998 Annual Environmental Operating Report Retention Number 4.5



. .



U. S. Nuclear Regulatory Commission Page 3

1. K. 1. 1.

C0899-05

- 1 <u>-</u>

Sec. 1

Ъ.

5

٠,

5

-

## D. M. Fitzgerald/J. P. Carlson bc:

, '

- FOLIO, w/enclosure R. C. Godley/G. P. Arent/J. Burford M. W. Rencheck/D. J. Garner/S. A. Greenlee
- J. F. Stang, Jr., NRC Washington, DC w/enclosure