## JUL 17 1986

Docket No. 50-315 Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

## Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. E. Jones of this office on June 26, 1986, of activities at the D. C. Cook Nuclear Power Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. G. Caple at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely

J. J. Harrison, Chief Engineering Branch

Enclosure: Inspection

Reports No. 50-315/86026(DRS);

and No. 50-316/86026(DRS)

8607230057 860717 PDR ADDCK 05000315 Q PDR

See Attached Distribution

RIII SWH Judones/1c 7/17/86 RIII STALF Danielson RIII Burgess

Hayrison

A CONTRACTOR OF A CONTRACTOR ASSOCIATION A

A STATE OF THE STA

and the second of the second o

A STATE OF THE STA

The second second second

 $(\mathbf{x}_{i}, \mathbf{x}_{i}, \mathbf{x$ 

The face

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

THE REPORT OF THE PROPERTY OF