

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 8804150050 DOC. DATE: 88/04/11 NOTARIZED: NO DOCKET #  
 CIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME AUTHOR AFFILIATION  
 HARRISON, J.J. Region 3, Ofc of the Director  
 RECIP. NAME RECIPIENT AFFILIATION  
 ALEXICH, M.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Safety Insp Repts 50-315/88-13 & 50-316/88-15 on 880315-31. No violations noted. R

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 246  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response I  
 D

NOTES:

	RECIPIENT		COPIES		
	ID CODE/NAME		LTR	ENCL	
	PD3-3 PD		1	1	/
		STANG, J	2	2	A
INTERNAL:	AEOD	DEDRO	1	1	D
	NRR MORISSEAU, D	NRR/DLPQ/PEB 11	1	1	D
	NRR/DLPQ/QAB 10	NRR/DOEA DIR 11	1	1	D
	NRR/DREP/EPB 10	NRR/DREP/RPB 10	2	2	S
	NRR/DRIS DIR 9A	NRR/PMAS/IIRB12	1	1	
	OE LIEBERMAN, J	OGC 15-B-18	1	1	
	<u>REG FILE</u> 02	RES/DRPS DIR	1	1	
	RGN3 FILE 01				
INTERNAL:	LPDR	NRC PDR	1	1	
	NSIC		1	1	

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 22

R  
I  
D  
S  
/  
A  
D  
D  
S

APR 11 1988

Docket No. 50-315  
Docket No. 50-316

Indiana Michigan Power Company  
ATTN: Mr. Milton P. Alexich  
Vice President  
Nuclear Operations Division  
1 Riverside Plaza  
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. H. Neisler of this office on March 15-31, 1988, of activities at the D. C. Cook Nuclear Power Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74, and to the discussion of our findings with Mr. W. G. Smith, Jr. and others of your staff at the conclusion of the inspection. The purpose of this inspection was to examine the licensee's implementation of commitments to Generic Letter 83-28.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by J. J. Harrison

J. J. Harrison, Chief  
Engineering Branch

Enclosure: Inspection Reports  
No. 50-315/88013(DRS);  
No. 50-316/88015(DRS)

See Attached Distribution

RIII  
*RW*  
Neisler/jk  
04/08/88

RIII  
*RJB*  
Burgess  
04/16/88

RIII  
*RJG*  
Gardner  
04/08/88

RIII  
*JJA*  
Harrison  
04/11/88

8804150050 880411  
PDR ADDCK 05000315  
Q DCD

*111*  
*IEC1*

Indiana Michigan Power Company

2

APR 11 1988

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager  
DCD/DCB (RIDS)

Licensing Fee Management Branch  
Resident Inspector, RIII

Ronald Callen, Michigan  
Public Service Commission

EIS Coordinator, USEPA  
Region 5 Office

Michigan Department of  
Public Health