REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

DOC.DATE: 89/04/06 NOTARIZED: NO DOCKET # CESSION NBR:8904170220 ACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000315 05000316 AUTHOR AFFILIATION AUTH.NAME GREGER, L. Region 3, Ofc of the Director

RECIPIENT AFFILIATION RECIP.NAME

Indiana Michigan Power Co. (formerly Indiana & Michigan EleR ALEXICH, M.P.

SUBJECT: Forwards Safety Insp Repts 50-315/89-13 & 50-316/89-13

on 890327-28. No violations noted.

D DISTRIBUTION CODE: IE35D COPIES RECEIVED:LTR ENCL SIZE: TITLE: Emergency Preparedness-Appraisal/Confirmatory Action Ltr/Exercise

I

NOTES:

	RECIPIENT ID CODE/NAME PD3-1 PD	COPIES LTTR ENG 1 · 1	RECIPIENT CL ID CODE/NAME STANG,J	COPIES LTTR ENCI 1 1	. A
INTERNAL:	NRR/DREP/EPB 10 NUDOCS-ABSTRACT REG_FILE 02 RGN2/DRSS/EPRPB	1 1 1 1 1 1 1 1	NRR/PMAS/ILRB12 OC/LFMB RGN3 FILE 01	1 1 1 0 1 1	D D
EXTERNAL:	LPDR NSIC	1 1 1 1	NRC PDR	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

DERES SON BURNERS

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR ENCL 11 • • • •

Docket No. 50-315 Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. Milton P. Alexich
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Ms. M. J. Smith of this office on March 27-28, 1989, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operation Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. G. Smith and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

L. Robert Greger, Chief Reactor Projects Branch

870406 05000315 PDC

Enclosure: Inspection Reports
No. 50-315/89013(DRSS);

No. 50-316/89013(DRSS)

See Attached Distribution

 yer
 yer

 RIII
 RIII

 دلاح
 MS

 Smith/jh
 Snell

 4/5/29
 4/5/29

RIII Burgess 4(6(8) RIII White Ables Wareger TE33

Distribution

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health
D. Bement, FEMA, RV
W. Travers, EPB, NRR