

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

SESSION NBR: 8908110150 DOC. DATE: 89/08/01 NOTARIZED: NO DOCKET #
 ACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME: AXELSON, W.L. AUTHOR AFFILIATION: Region 3, Ofc of the Director
 RECIP. NAME: ALEXICH, M.P. RECIPIENT AFFILIATION: American Electric Power Co., Inc.

SUBJECT: Forwards Safety Insp Repts 50-315/89-21 & 50-316/89-21 on 890607-0718 & notice of violation.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+19
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD3-1 PD	1 1	GIITTER, J.	1 1
INTERNAL:	AEOD	1 1	AEOD/DEIIB	1 1
	AEOD/TPAD	1 1	DEDRO	1 1
	NRR SHANKMAN, S	1 1	NRR/DEST DIR	1 1
	NRR/DLPQ/PEB	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	OE LIEBERMAN, J	1 1	OGC/HDS1	1 1
	REG FILE 02	1 1	RES MORISSEAU, D	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 23

R
I
D
S
/
A
D
D
S

AUG 1 1989

Docket No. 50-315
No. 50-316

American Electric Power Service
Corporation
Indiana Michigan Power Company
ATTN: Mr. M.P. Alexich
Vice President - Nuclear
Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen and D. G. Passehl of this office on June 7 through July 18, 1989 of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff at the conclusion of the inspection.

This refers also to the special evaluation of a Unit 1 CD diesel overspeed event which was performed by Mr. E. Tomlinson of the NRC Office of Nuclear Reactor Regulation, and to the management meeting of June 22, 1989, which was held in NRC Region III and involved a presentation and discussion on several matters of mutual interest.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

8908110150 890801
PDR ADOCK 05000315
PDC
Q

11
IEDI

American Electric Power
Service Corporation

2

AUG 1 1989

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W. L. Axelson"

W. L. Axelson, Chief
Reactor Projects Branch 2

Enclosures:

1. Notice of Violation
2. Inspection Reports
 No. 50-315/89021(DRP);
 No. 50-316/89021(DRP)

cc w/enclosures:

W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health
J. Gitter, LPM, NRR
E. Tomlinson, NRR

RIII
Burgess/cs
8/1/89

RIII
Axelson

