

90-22

RCI 113...

DECLASSIFIED
RIP

Docket No. 50-315
No. 50-316

American Electric Power Service Corporation
Indiana Michigan Power Company
ATTN: Mr. M. P. Alexich
Vice President - Nuclear
Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by J. A. Isom and D. G. Passehl of this office on August 29 through October 9, 1990, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74 and to the discussion of our findings with A. A. Blind, and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

B. Clayton, Chief
Reactor Projects Branch 2


Enclosure:

- 1. Notice of Violation
- 2. Inspection Reports
 - No. 50-315/90022(DRP);
 - No. 50-316/90022(DRP)

See Attached Distribution

9011270062 901119
PDR ADOCK 05000315
Q FIC

IFD
11



NOV 1 1990

American Electric Power Service Corporation

2

Distribution

cc w/enclosures:

A. A. Blind, Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
James R. Padgett, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health
T. Colburn, LPM, NRR

RIII
Bywater
11/9/90

ES
RIII
EAS for
Burgess/
11-9-90

Yes
RIII BC
Clayton
11/16/90





UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

Docket No. 50-315
No. 50-316

American Electric Power Service
Corporation
Indiana Michigan Power Company
ATTN: Mr. M. P. Alexich
Vice President - Nuclear
Operations Division
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by J. A. Isom and D. G. Passehl of this office on August 29 through October 9, 1990, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74 and to the discussion of our findings with A. A. Blind, and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,

B. Clayton, Chief
Reactor Projects Branch 2

Enclosure:

1. Notice of Violation
2. Inspection Reports
No. 50-315/90022(DRP);
No. 50-316/90022(DRP)

See Attached Distribution



NOV 1 1990

American Electric Power Service
Corporation

2

Distribution

cc w/enclosures:

A. A. Blind, Plant Manager

DCD/DCB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

James R. Padgett, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

T. Colburn, LPM, NRR

