

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9110010249 DOC. DATE: 91/09/24 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
 AUTH. NAME AUTHOR AFFILIATION
 FITZPATRICK, E. American Electric Power Co., Inc.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

see Rpt

SUBJECT: Forwards "Evaluation of Tritium Migration in Aquifer of DC Cook Nuclear Plant & Surrounding Communities."

DISTRIBUTION CODE: C001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 + 100
 TITLE: Licensing Submittal: Environmental Rept Amdt & Related Correspondence

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA COLBURN, T.	3 3 1 1	PD3-1 PD	1 1
INTERNAL:	NRR/DET/ESGB 8D	1 1	OC/LEMB	1 0
	OGC/HDS2	1 0	REG FILE 01	1 1
	RGN3 DRSS/RPB	1 1		
EXTERNAL:	EG&G SIMPSON, F	2 2	'NRC PDR	1 1
	NSIC	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 12

ER

R
I
D
S
/
A
D
S
/
A
D
D
S
/
A
D
D
S

American Electric Power
Service Corporation
1 Riverside Plaza
Columbus, OH 43215
614 223 1000



AEP:NRC 1164

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74
EVALUATION OF TRITIUM MIGRATION IN THE AQUIFER OF THE DONALD C.
COOK NUCLEAR PLANT AND SURROUNDING COMMUNITIES

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555

ATTN: A. B. Davis

September 24, 1991


Dear Mr. Davis:

As requested by Mr. M. C. Schumacher of your staff, enclosed is the Evaluation of Tritium Migration in the Aquifer of the Donald C. Cook Nuclear Plant and Surrounding Communities. The enclosed evaluation was prompted by radiochemical analyses of onsite environmental monitoring well samples which detected tritium in concentrations greater than preoperational levels. As a result of this finding we were requested by your staff to evaluate the potential impact on offsite members of the public who might draw water from the affected aquifer for domestic use.

Based on our analysis of samples taken from offsite domestic wells we have concluded that the presence of tritium in the onsite environmental monitoring well samples results in no affect on public health and safety. We have, however, initiated revisions to our radiological environmental monitoring program to include routine sampling of additional wells in order to confirm that this continues to be the case in the future.

9110010249 910924
PDR ADOCK 05000315
P PDR

COOL 1/1



Mr. A. B. Davis

-2-

AEP:NRC:1164

This document has been prepared following Corporate procedures that incorporate a reasonable set of controls to ensure its accuracy and completeness prior to signature by the undersigned.

Sincerely,



E. E. Fitzpatrick
Vice President

tjw

Enclosure

cc: D. H. Williams, Jr. w/o attachment
A. A. Blind - Bridgman w/o attachment
J. R. Padgett w/o attachment
G. Charnoff w/o attachment
NFEM Section Chief w/o attachment
NRC Resident Inspector - Bridgman w/o attachment