

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9304300071 DOC.DATE: 93/04/23 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316
 AUTH.NAME AUTHOR AFFILIATION
 WRIGHT,G.C. Region 3 (Post 820201)
 RECIP.NAME RECIPIENT AFFILIATION
 FITZPATRICK,E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards insp repts 50-315/93-06 & 50-316/93-06 on
 930322-0401.No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+10
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	. RECIPIENT		COPIES		. RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME		LTR	ENCL
	PD3-1 PD	1	1		DEAN,W	1	1
INTERNAL:	AEOD/DEIB	1	1	AEOD/DSP/TPAB	1	1	
	AEOD/TTC	1	1	DEDRO	1	1	
	NRR/DORS/OEAB	1	1	NRR/DRCH/HHFB	1	1	
	NRR/DRIL/RPEB	1	1	NRR/DRSS/PEPB	1	1	
	NRR/PMAS/ILPB1	1	1	NRR/PMAS/ILPB2	1	1	
	NUDOCS-ABSTRACT	1	1	OE DIR	1	1	
	OGC/HDS2	1	1	REG ELDE 02	1	1	
	RES MORISSEAU,D	1	1	RGN3 FILE 01	1	1	
EXTERNAL:	EG&G/BRYCE,J.H.	1	1	NRC PDR	1	1	
	NSIC	1	1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 21 ENCL 21

map
dlp



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

April 23, 1993

Docket No. 50-315
Docket No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
Nuclear Operations Division
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This letter refers to the routine safety inspection conducted by Messrs. M. P. Huber, J. F. Smith and G. D. Replogle of this office on March 22 through April 1, 1993. The inspection included a review of activities authorized for your D. C. Cook Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

The areas examined during the inspection are identified in the report. These areas consisted primarily of a review of the implementation of the D. C. Cook Motor Operated Valve Program established in response to Generic Letter 89-10. Within this area, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

G. C. Wright
G. C. Wright, Chief
Engineering Branch

Enclosures:

1. Inspection Reports
No. 50-315/93006(DRS);
No. 50-316/93006(DRS)
2. MOV Review Listing

See Attached Distribution

9304300071 930423
PDR ADOCK 05000315
Q PDR

Public-IE01

April 23, 1993

Distribution

cc w/enclosures:

A. A. Blind, Plant Manager
A. Gort, MOV Coordinator
OC/LFDCB
Resident Inspector, RIII
James R. Padgett, Michigan
Public Service Commission
EIS Coordinator, USEPA,
Region V Office
Michigan Department of
Public Health
D. C. Cook LPM, NRR
T. Scarbrough, NRR
J. Norberg, NRR
P. Eapen, RI
F. Jape, RII
T. Westerman, RIV
P. Narbut, RV