

FORD 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9307130058 DOC. DATE: 93/07/01 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana M 05000316

AUTH. NAME AUTHOR AFFILIATION
 MCCABE, B.C. Region 3 (Post 820201)
 RECIP. NAME RECIPIENT AFFILIATION
 FITZPATRICK, E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards insp repts 50-315/93-13 & 50-316/93-13 on 930501-0615. No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 3+14
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL
	PD3-1	PD	1	1		DEAN, W		1	1
INTERNAL:	AEOD/DEIB		1	1		AEOD/DSP/ROAB		1	1
	AEOD/DSP/TPAB		1	1		AEOD/TTC		1	1
	DEDRO		1	1		NRR/DORS/OEAB		1	1
	NRR/DRCH/HHFB		1	1		NRR/DRIL/RPEB		1	1
	NRR/DRSS/PEPB		1	1		NRR/PMAS/ILPB1		1	1
	NRR/PMAS/ILPB2		1	1		NUDOCS-ABSTRACT		1	1
	OF DIR		1	1		OGC/HDS2		1	1
	<u>REG FILE</u>	02	1	1		RES/HFB		1	1
	RGN3	FILE 01	1	1					
EXTERNAL:	EG&G/BRYCE, J.H.		1	1		NRC PDR		1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 22



JUL 0 1 1993

11/2/93

Docket No. 50-315
No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom, D. J. Hartland, E. R. Schweibinz, and R. C. Paul of this office on May 1, through June 15, 1993, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection. This refers also to a routine management meeting conducted at the NRC Region III office on May 13, 1993.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. Items discussed at the management meeting are also summarized.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosure(s), and your response(s) to this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original signed by
B. C. McCabe, Acting Chief
Reactor Projects Section 2A

Enclosure(s):
Inspection Reports
No. 50-315/93013(DRP);
No. 50-316/93013(DRP)

YES
RIII *ead*
Schweibinz
7-1-93

RIII
SM for
Paul
(para 4)
7/1/93

RIII
dp
Pirok

Yes
RIII
B.C.M.
McCabe
7/1/93

TEC 1

930713005B 930701
PDR ADDOCK 05000315
G PDR



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JUL 01 1993

Docket No. 50-315
No. 50-316

Indiana Michigan Power Company
ATTN: Mr. E. E. Fitzpatrick
Vice President
1 Riverside Plaza
Columbus, OH 43216

Dear Mr. Fitzpatrick:

This refers to the routine safety inspection conducted by J. A. Isom, D. J. Hartland, E. R. Schweibinz, and R. C. Paul of this office on May 1, through June 15, 1993, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74, and to the discussion of our findings with A. A. Blind and others of your staff at the conclusion of the inspection. This refers also to a routine management meeting conducted at the NRC Region III office on May 13, 1993.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. Items discussed at the management meeting are also summarized.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosure(s), and your response(s) to this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

B. C. McCabe, Acting Chief
Reactor Projects Section 2A

Enclosure(s):
Inspection Reports
No. 50-315/93013(DRP);
No. 50-316/93013(DRP)

See Attached Distribution

JUL 01 1993

Indiana Michigan Power Company

2

Distribution

cc w/enclosures:

A. A. Blind, Plant Manager

DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII

James R. Padgett, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region 5 Office

Michigan Department of

Public Health

D. C. Cook, LPM, NRR