

UNIT 2 1990 NIS-2 INDEX

<u>COMPONENT NUMBER</u>	<u>JOB ORDER</u>	<u>DESCRIPTION</u>	<u>ISI CLASS</u>
2-CS-300W	B007224	REPLACED DISC	2
*2-CS-321	B000122	REPLACED STUDS	2
*2-CS-329-L1	B000124	REPLACED STUDS AND NUTS	1
*2-CS-523-1	B000108	REPLACED STUDS	2
*2-CS-523-2	B000128	REPLACED STUDS AND NUTS	2
*2-CS-523-3	B000109	REPLACED STUDS AND NUTS	2
*2-CS-523-4	B000127	REPLACED STUDS AND NUTS	2
2-CS-535	B015290	REPLACED BONNET AND PLUG	2
2-CS-536	B015302	REPLACED PLUG	2
2-CS-536	B016726	REPLACED DISC	2
*2-CTS-138W	B016546	REPAIRED VALVE COVER	2
*2-DCR-320	B018578	REPLACED PLUG	2
*2-FW-S12	B004819	REPLACED SNUBBER	2
*2-FW-S2U	B004820	REPLACED LOAD PIN	2
*2-FW-S7	B051200	REPLACED SNUBBER	2
*2-GCTS-S115S	B050176	REPLACED SNUBBER	2
*2-GCTS-S116W	B050175	REPLACED SNUBBER	2
*2-GRC-S609	B007221	REPLACED CONTROL VALVE	1
*2-GRC-S629	B004526	REPLACED LOAD PIN	1
*2-IFX-215-OR	B016537	REPLACED FLANGE STUDS	2
*2-IFX-220-OR	B016741	REPLACED FLANGE STUDS AND NUTS	2
**2-IMO-316	C4362-4	REPLACED STUDS AND NUTS	2
*2-IMO-325	B018041	REPLACED STUDS AND NUTS	1
*2-IMO-326	B016836	REPLACED STUDS	1
2-IPX-254-V1	B016699	REPAIRED VALVE	2
*2-MCM-231	B006833	REPLACED BONNET, REPAIRED BODY	2
*2-MRV-210	B011574	REPLACED STUDS AND NUTS REPAIRED VENT PIPE	2
2-MRV-211	B012012	REPLACED PLUG	2
2-MRV-212	B012013	REPLACED PLUG	2
*2-MRV-220	B001150/ B011576	REPLACED STUDS, REPAIRED BODY AND VENT PIPE	2
2-MRV-222	B003101	REPLACED PLUG	2
*2-MRV-223	B000300	REPAIRED BONNET	2
2-MRV-223	B016330	REPLACED PLUG, STUDS, AND NUTS, REPAIRED VALVE BODY AND SPACER	2

9401120034 931220
PDR ADDCK 05000316
G PDR

<u>COMPONENT NUMBER</u>	<u>JOB ORDER</u>	<u>DESCRIPTION</u>	<u>ISI CLASS</u>
*2-MRV-230	B011578	REPLACED STUDS AND NUTS. REPAIRED VENT PIPE	2
2-MRV-232	B018393	REPLACED DISC	2
2-MRV-233	B013353	REPLACED PLUG	2
*2-MRV-240	B011580	REPLACED STUDS AND NUTS REPAIRED VENT PIPE	2
*2-MS-135-1	B054408	REPLACED VALVE AND 2' OF PIPE	2
*2-MS-135-2	B008101	REPLACED VALVE AND 2' OF PIPE	2
2-MS-135-3	B005138	REPLACED VALVE AND 3' OF PIPE	2
*2-MS-135-4	B054410	REPLACED VALVE AND 2' OF PIPE	2
*2-MSS-4	B004818	REPLACED SNUBBER AND ROD EYE	2
2-NRV-151	B004664	REPLACED PLUG	1
2-NRV-151	B015468	REPLACED PLUG	1
2-NRV-152	B004665	REPLACED PLUG	1
*2-NRV-153	B004666	REPLACED PLUG AND STUD	1
2-NRV-163	B008108	REPLACED PLUG, STUDS AND NUTS	1
**2-OME-3-1-HSD-3L	REPORT # 42477-3	REPLACED PISTON AND PISTON ROD	1
*2-PS-05	B006906	REPAIRED WELD	2
2-QRV-251	B016844	REPLACED PLUG	2
*2-QRV-160	B003799	REPLACED STUDS AND NUTS	1
*2-QRV-161	B018107	REPLACED STUDS AND NUTS	1
*2-QRV-162	B018108	REPLACED STUDS AND NUTS	1
*2-QRV-303	B016150	REPLACED STUDS AND NUTS	2
*2-QRV-400	B004697	REPLACED BONNET, STUDS & NUTS	2
*2-QRV-51	B004684/ B005618	REPLACED STUDS AND NUTS REPLACED STUDS	1 1
*2-RC-103-L1	B015210	REPLACED BONNET	1
2-RC-103-L1	0024760	REPLACED DISC	1
*2-RC-103-L2	B013598	REPLACED BONNET	1
*2-RC-103-L3	B053937	REPLACED BONNET AND DISC	1
*2-RC-103-L4	0024709	REPLACED BONNET	1
*2-RH-139	B002474	REPLACED STUDS AND NUTS	2
*2-RO-18E	B016742	REPLACED STUDS	2
*2-SI-158-L1	B018951	REPLACED STUDS	1
*2-SI-158-L1	B004670	REPLACED BONNET, STUDS & NUTS	1
2-SI-158-L2	B002505	REPLACED DISC	1
*2-SI-158-L4	B000021	REPLACED STUDS AND NUTS	1
*2-SI-158-L4	B018952	REPLACED STUDS	1
*2-SI-170-L1	B000057	REPLACED STUDS AND NUTS	1
*2-SI-170-L3	B003100	REPLACED STUDS AND NUTS	1

100-100000-100000

100

100

100

100-100000-100000

100-100000-100000

100

<u>COMPONENT NUMBER</u>	<u>JOB ORDER</u>	<u>DESCRIPTION</u>	<u>ISI CLASS</u>
*2-STN-42E	B016147	REPLACED STUD	2
*2-SV-103	B000175	REPLACED FLANGE BOLTING	2
*2-SV-104E	B000176	REPLACED FLANGE BOLTING	2
*2-SV-104E	0032602	REPLACED VALVE	2
*2-SV-104W	0032641	REPLACED VALVE	2
*2-SV-105E	B000177	REPLACED FLANGE BOLTING	2
*2-SV-105W	B000178	REPLACED FLANGE BOLTING	2
*2-SV-1A-2	B050036	REPLACED DISC & FLANGE BOLTING	2
*2-SV-1A-3	B002564	REPLACED FLANGE BOLTING	2
*2-SV-1A-4	B008166	REPLACED FLANGE BOLTING	2
*2-SV-1B-2	B050038	REPLACED DISC & FLANGE BOLTING	2
*2-SV-1B-4	B050034	REPLACED FLANGE BOLTING	2
*2-SV-2A-2	B002557	REPLACED FLANGE BOLTING	2
*2-SV-2A-4	B002565	REPLACED FLANGE BOLTING	2
*2-SV-2B-1	B050037	REPLACED FLANGE BOLTING	2
*2-SV-3-4	B050033	REPLACED FLANGE BOLTING	2
*2-SV-45A	B008163	REPLACED VALVE AND INLET STUDS/NUTS	1
*2-SV-45B	B006122	REPLACED STUDS AND NUTS	1
*2-SV-45C	B004913	REPLACED VALVE AND NUTS	1
*2-SV-51	B000031	REPLACED VALVE & FLANGE BOLTS	2
2-SV-51	B015472	REPLACED DISC	2
2-SV-52	B016777	REPLACED FLANGE BOLTING	2
*2-SV-54	B016583	REPLACED FLANGE BOLTING	2

* These components were previously identified within the required reporting period. The NIS-2 reports for these components have been revised, primarily to reflect the correct Code of Construction in Part 5a.

** These components were worked during the 1992 outage but were inadvertently overlooked during the reporting period following the 1992 outage

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100